Competent Person Written Report (Both passive and active detection are completed) CP Signature : Name: John Chan Approval No. : CP00000 Date : 20/9/2017 Directly Employed by: A Consultant Limited

			Re	cord No. : <u>266</u>	5366EMSD
To: Forema	n (Post)	of B Compa	arry Limited	me of site cor king party)	ntractor or other
Part A - Basic In	formation				
I John	Chan th	ne Competent Pers	on of underground e	electricity cabl	e detection
Approval No.:	CP00000	expiry date:	1/12/2017		
in accordance with E	lectricity Supply Li	nes (Protection) Re	gulation,		
from <u>2017</u> yea	r <u>9</u> month_	18 day 10	hour 0 min	ute	
to <u>2017</u> yea	r <u>9</u> month_	20 day <u>15</u>	hour 0 min	ute	
		eet Carpark, Tai Po	•	الالحاليم مسام	and all many of
undertook undergrou and depth on site.	nd cable detection	n (both active and p	assive detection) ar	nd marked the	cable alignment
Part B - Equipme	ent used during	g underground o	cable detection		
Receiver	Brand name:	С	Serial N	lo.:	456123
	Model No.:	123	Calibration reco		15/8/2017
Transmitter	Brand name:	С	Serial N	lo.:	123456
	Model No.:	123a	Calibration rec		15/8/2017
			Frequen	cy: <u>8kHz</u> ,	11kHz & 33kHz
Part C - Matters requiring particular attention Having found that the quantity of exposed cable was not matched with the cable shown in the underground cable plan, we discussed this issue with the electricity supplier on 19.9.2017 and the result was as follow: The electricity supplier confirmed that the location of the part of the cable shown in the cable plan had been altered.					
The above mentioned she was directly super	-			ssistance o <u>f</u>	Peter MA_ and he/
CP s	ignature:	1 Chully		Date:	20/9/2017
CP assistant s	ignature:	May		Date:	20/9/2017
Name	e: (Peter MA)		

Pa	rt D - Attachments	
1	Work Procedure	(Total 1 sheets)
2	Measurement record	(Total 1 sheets)
3	Underground Cable Alignment Layout Plan by Active Detection	(Total 1 sheets)
4	Photos showing toroidal active detection and site markings for cable alignment and depth	(Total 6 Nos.)
5	Electricity supplier's advice, such as advice sought from the electricity supplier upon detecting major deviations of cable alignment on site from electricity supplier's cable plans (if any)	(Total 1 sheets)
6	Electricity supplier's cable plans	(Total 1 sheets)
7	Site briefing	(Total 1 sheets)
8	Others:	(Total 1 sheets)

CP Written Report Work Procedure

Record No.:	266366EMSD	Page:	3	
Working Place :	Opposite to Tai Wai Street Carpark, Tai Po, N.T.			
Nature of Work :	Trench work			

Date / Time	Cable Detection Work Procedure	Relevant Photo No.
18/9/2017 at 10:30	Having obtained the location plan of the construction site and the corresponding underground cable plan, passive detection was being planned to carry out.	
18/9/2017 at 11:00	Passive detection was carried out.	Photo 1 and Photo 2
19/9/2017 at 10:00	Supervion of trial holes excavation until the target cable was exposed.	
19/9/2017 at 12:00	Having found that the quantity of exposed cable was not matched with the cable shown in the underground cable plan, we liased with CLP.	
19/9/2017 at 13:00	Having liased with CLP, CLP confirmed the above cable location had been altered. Therefore, the quantity of the exposed cable was correct.	
20/9/2017 at 10:00	Carried out torodial active detection to identify the alignment & depth of the un-exposed underground cable	Photo 3
20/9/2017 at 11:00	Marked the cable alignment & depth on site & took photos for record purpose	Photo 4, photo 5 and Photo 6
20/9/2017 at 11:30	Measured and recorded the distance between the detedtion point & the refernce point A & B	
20/9/2017 at 13:30	Submission of competent person writtten report to the working party	
20/9/2017 at 14:30	The working party arranged site briefing given by the competent person to ensure that the site personnel were conversant with the contents of the report and the site personnel was requested to sign for record purpose.	

CP Written Report Measurement Record

Record No. : 266366EMSD	Page: 4
	no. control signal cable
Cable No. <u>123456</u>	Voltage: <u>no.</u> 380/220V <u>no.</u> 132kV
Cable	<u>1 no.</u> 11kV <u>no.</u> 275kV
Quantity: 1	<u>no.</u> 22kV <u>no.</u> 400kV
	no. Control signal cable


Cable detection point	Distance from reference point (A)*		Distance from reference point (B)*		Depth from ground level*		Remarks
	Actual (m)	Ratio 1:	Actual (m)	Ratio 1:	Passive detection^ (mm)	Active detection (mm)	(Cable information)
P1	10.8	36.0	1.8	6.0	800	800	1 no. of 11kV underground cable
P2	9.0	30.0	3.6	12.0	750	790	1 no. of 11kV underground cable
P3	7.2	24.0	5.4	18.0	800	810	1 no. of 11kV underground cable
P4	4.2	14.0	8.4	28.0	750	800	1 no. of 11kV underground cable
P5	2.7	9.0	10.2	34.0	750	800	1 no. of 11kV underground cable
P6	1.5	5.0	11.4	38.0	750	800	1 no. of 11kV underground cable

^{*} Deviation is less than 25%

[^] depth measurement from passive detection is not accurate and the figure is for reference only

CP Written Report Underground Cable Layout Plan

Record No.: 266366EMSD	Page:	5	
------------------------	-------	---	--



Legend:
(For reference only)

X: Measurement Point

D: Cable Depth (mm)
----: Cable Alignment

A: Reference Point A

B: Reference Point B

Remarks: The cable layout plan should include all the relevant details to clearly indicate the cable location such as site area, cable alignment, reference point, sequence number of detection points, cable depth, cable quantity, cable voltage level, trial hole location, kerb, building line, manhole, etc.

Ratio 1:300

CP Written Report Photos for Active Detection

Record No. :266366EMSD Page : 6

Photo 1 (Passive detection was carried out)







Photo 3 (Carried out torodial active detection)

Photo 4 (Marked the cable alignment & depth on site)





Photo 5(Marked the cable alignment & depth on site)

Photo 6 (recorded Marked the cable alignment & depth)






CP Written Report				
Record No.: 266366EMSD	Page:			
Electricity supplier's advice, such as advice sought from the deviations of cable alignment on site from electricity supplies				
The working party has requested cable plans from the electricity supplier on				
Having found that the quantity of exposed cable was not matche plan, we discussed this issue with the electricity supplier on 19.9 The electricity supplier confirmed that the location of the part of taltered.	.2017 and the result was as follow:			

CP Written Report Cable Layout plan of Electricity Supplier

Record No.: <u>266366EMSD</u> Page: <u>8</u>



		CP Written report		
Red	cord No.: 26636	B6EMSD Pa	age: 9	
Site	Briefing			
of exc	avator/machine and	t of the Competent Person Written Report to the following site personnel, such d workers engaged in excavation work, including the meaning of site markings, ge and the required safety precautions, and other details of this report.		
1	Signature :	Date : 20/9/2017		
	Name/ Post :	(Jasper POON / Site agent)		
2	Signature :	15. Atalust Date: 20/9/2017		
	Name/ Post :	(Kenneth MAK / Foreman)		
3	Signature :	Date : 20/9/2017		
	Name/ Post :	(David CHEUNG / Operator)		
4	0'	C 1 2 1		
4	Signature : Name/ Post :			