

Our reference 本署檔號 :
(28) in EMSD/LESD 7-02/04

Your reference 來函檔號 :

Telephone 電話號碼: 2808 3115
Facsimile 圖文傳真: 2504 5970

13 October 2006

All Registered Lift Contractors/Engineers

Dear Sirs,

Circular No. 10/2006
Preventing Blockage of Oil Holes in Gearbox of Lift Machine

Please be reminded that you have to take effective measures to prevent blockage of oil holes in the gearbox of the lift machine under your maintenance.

A recent passenger entrapment in a lift revealed that the sticky residue accumulated in the interior of the gearbox could block the oil hole for lubricating the driving shaft causing the gearbox to seize up. Such accumulated sticky residue should be removed periodically.

Yours faithfully,



(G.M.W. CHUI)
for Director of Electrical & Mechanical Services

c.c. AD/BS,
Director of Housing (Attn.: TS/2),
Director of Buildings (Attn.: CBS/Legislation),
Director of Fire Services (Attn.: Fire Safety Command)
The Hong Kong General Union of Lift and Escalator Employees
G28/28 SF1 Pt. IV