Quarterly Contractors' Performance Rating (CPR) of Registered Lift Contractors

(Assessment period: from July 2024 to June 2025 (Note 1)
(in alphabetical order based on the Services Quality Performance Rating)

Name of Contractor	Contractor No.	Safety Performance Rating (Note 2)	Services Quality Performance Rating (Note 2)
Anlev Elex Elevator Ltd.	RLC92004	*	****
Antonfield Engineering Co., Ltd.	RLC95002	*	****
Cheerwell Engineering Limited	RLC96002	*	****
Chun Ming Elevator Co. Ltd.	RLC93002	*	****
CKP Building Service Systems Ltd.	RLC85001	*	****
Elevator Parts Engineering Company Limited	RLC78001	*	****
Eugene Engineering Co. Limited	RLC03002	*	****
German Edunburgh Elevator & Escalator (HK) Ltd.	RLC17001	*	****
Jekco Elevators Ltd.	RLC97001	*	****
Mitsubishi Elevator Hong Kong Company Limited	RLC88005	*	****
Ring Hing Engineering Services Co. Ltd.	RLC97004	*	****
Sun Fai Engineering & Equipment Co., Ltd.	RLC02002	*	****
Taizoom Elevator Co.(H.K.)Ltd.	RLC10001	*	****
Tak Lee Elevator Engineering Co., Ltd.	RLC02001	*	****
Techfaith Engineering Limited	RLC00002	*	****
Toki Elevator Engineering Ltd.	RLC85002	*	****
Vertex Engineering Limited	RLC00001	*	****

Name of Contractor	Contractor No.	Safety Performance Rating (Note 2)	Services Quality Performance Rating (Note 2)
Associated Engineers, Ltd.	RLC01003	*	***
Chevalier (HK) Limited	RLC69001	*	***
Chun Ming Engineering Co. Ltd.	RLC88002	*	***
Fujitec (HK) Co., Ltd.	RLC85005	*	***
Hitachi Elevator Engineering Co. (HK) Ltd.	RLC67001	*	***
Holake Hong Kong Lifts Ltd.	RLC80005	*	***
KONE Elevator (HK) Ltd.	RLC87001	*	***
Lighthouse Elevator Engineering Limited	RLC98003	*	***
Schindler Lifts (Hong Kong) Ltd.	RLC74002	*	***
Shan On Engineering Company Limited	RLC73002	*	***
Sigma Elevator (HK) Ltd.	RLC04002	*	***
The Express Lift Co., Ltd.	RLC94001	*	***
Fuhitabishi Engineering Limited	RLC20003	*	**
Wemaintain Limited	RLC24002	*	**
Rich Mark Engineering Limited	RLC99001	*	
Otis Elevator Company (H.K.) Ltd.	RLC75004	(Note 3a)	
TK Elevator (HK) Limited	RLC96001	(No	ote 3b)

Note 1:

The list of performance rating only shows the performance rating of the contractor who had five or more lifts inspected by the EMSD during the assessment period. In other words, for those contractors having less than five lifts inspected by the EMSD during the assessment period [refer to Table (a)], and contractors not undertaking any lift maintenance works during the assessment period [refer to Table (b)], their performances are not included in the list of performance rating.


Contractors having less than five lifts inspected by the EMSD during the assessment period: (a)

Name of Contractor	Contractor No.
Association Electrical Engineering Limited	RLC02003
Best Vision Group Limited	RLC21001
Harbor Engineering Co. Limited	RLC02004
Hoi Fai Lift Eng. & Services Ltd.	RLC87006
Hongkong International Terminals Limited	RLC01004
Loedige Asia Limited	RLC07001
MTR Corporation Limited	RLC78003
Ryoden Elevator Company Limited	RLC64001

(b) Contractors not undertaking any lift maintenance works during the assessment period

N	lame of Contractor	Contractor No.
N	I/A	

Note 2:



In choosing a registered lift contractor for provision of maintenance services, apart from the price, the responsible person should also consider the registered contractor's background and scale, specific technical knowledge, availability of spare parts, details of maintenance works, time required, emergency response capability, as well as the latest performance rating. After considering these factors, if the responsible person decides to choose a registered contractor with no safety stars or with fewer quality stars under the Contractors' Performance Rating for provision of maintenance service, the EMSD suggests that the responsible person should step up the management and supervision of the contractor's performance. For instance, the responsible person may specify in the contract a requirement for regular submissions of operational reports of the lift with analysis of the working conditions, failure rates and failure modes. The responsible person should also hold regular meetings with the registered contractor and review the contractor's performance. If necessary, the responsible person should consider engaging an independent consultant to provide independent professional advice.

Note 3a : Occurrence of unintended car movement, thus served with one warning

letters. The records of non-compliance will be kept for one year until 1/2026.

Note 3b : Ineffective car door electrical interlock device was found, thus served with

one warning letters. The records of non-compliance will be kept for one year

until 2/2026.