

Quarterly Contractors' Performance Rating (CPR) of Registered Lift Contractors  
(Assessment period: from October 2015 to September 2016) (Note 1)  
(in alphabetical order based on the Services Quality Performance Rating)

Name of Contractor	Contractor No.	Safety Performance Rating (Note 2)	Services Quality Performance Rating (Note 2)
Anlev Elex Elevator Ltd.	RLC92004	★	★★★★★
Antonfield Engineering Co., Ltd. (Note 3)	RLC95002	★	★★★★★
Association Electrical Engineering Limited	RLC02003	★	★★★★★
Associated Engineers, Ltd.	RLC01003	★	★★★★★
Ben Fung Machineries & Engineering Ltd	RLC73001	★	★★★★★
Cheerwell Engineering Limited	RLC96002	★	★★★★★
CKP Building Service Systems Ltd.	RLC85001	★	★★★★★
Elevator Parts Engineering Company Limited	RLC78001	★	★★★★★
Hitachi Elevator Engineering Co. (HK) Ltd.	RLC67001	★	★★★★★
Hoi Fai Lift Engineering & Services Ltd.	RLC87006	★	★★★★★
Hongkong International Terminals Limited	RLC01004	★	★★★★★
Loedige Asia Limited	RLC07001	★	★★★★★
Sun Fai Engineering & Equipment Co., Ltd.	RLC02002	★	★★★★★
Tak Lee Elevator Engineering Co., Ltd.	RLC02001	★	★★★★★
Toki Elevator Engineering Ltd.	RLC85002	★	★★★★★

---

Vertex Engineering Limited	RLC00001	★	★★★★★
Chevalier (HK) Limited	RLC69001	★	★★★
Chun Ming Elevator Co. Ltd.	RLC93002	★	★★★
Chun Ming Engineering Co. Ltd.	RLC88002	★	★★★
Fujitec (HK) Co. Ltd.	RLC85005	★	★★★
KONE Elevator (HK) Ltd.	RLC87001	★	★★★
Mitsubishi Elevator Hong Kong Company Limited	RLC88005	★	★★★
Otis Elevator Company (HK) Limited	RLC75004	★	★★★
Ring Hing Engineering Services Co., Ltd.	RLC97004	★	★★★
The Express Lift Company Limited	RLC94001	★	★★★
Holake Hong Kong Lifts Ltd.	RLC80005	★	★★
Jekco Elevators Ltd.	RLC97001	★	★★
Rich Mark Engineering Limited	RLC99001	★	★★
Shan On Engineering Company Limited	RLC73002	★	★★
Taizoom Elevator Co.(H.K.)Ltd.	RLC10001	★	★★
Techfaith Engineering Limited	RLC00002	★	★★
ThyssenKrupp Elevator (HK) Limited (Note 4)	RLC96001	★	★★
Eugene Engineering Co. Limited	RLC03002	★	★
Nikkin Lifts & Escalators Limited	RLC91002	★	★
Lighthouse Elevator Engineering Limited	RLC98003	★	

---

Schindler Lifts (Hong Kong) Ltd. RLC74002 (Note 5a)

Sigma Elevator (HK) Ltd. RLC04002 (Note 5b)

Note 1:

The list of performance rating only shows the performance rating of the contractor who had five or more lifts being inspected by the EMSD during the assessment period. In other words, for those contractors having less than five lifts being inspected by the EMSD during the assessment period [refer to Table (a)], and contractors not undertaking any lift maintenance work during the assessment period [refer to Table (b)], their performances are not included in the list of performance rating.



(a) Contractors having less than five lifts being inspected by the EMSD during the assessment period:

Name of Registered Lift Contractor	Contractor No.
-	-

(b) Contractors not undertaking any lift maintenance work during the assessment period:


Name of Registered Lift Contractor	Contractor No.
Holake (HK) Ltd.	RLC76001
MTR Corporation Ltd.	RLC78003
Ryoden Elevator Company Limited	RLC64001

Note 2:

Rating	Description
	No non-compliance found in both safety and services quality aspects in two recent quarterly announcements (Safety Star awarded and the services quality performance index at 100 points in the two recent quarterly announcements)
	No non-compliance found in both safety and services quality aspects (performance index at 100 points in this quarterly announcement)



No non-compliance found in safety aspect and service quality performance index is between 90 and 99 points



No non-compliance found in safety aspect and service quality performance index is between 80 and 89 points



No non-compliance found in safety aspect and service quality performance index is between 70 and 79 points



No non-compliance found in safety aspect and service quality performance index is less than 70 points

Note 3:

The EMSD is conducting a disciplinary inquiry into a case relating to the lift safety and professional conduct of Antonfield Engineering Company Limited when carrying out lift works for a lift in Sai Ying Pun on 20 December 2012.

Note 4:

The Disciplinary Board has completed the disciplinary hearings on the performance of ThyssenKrupp Elevator (HK) Limited, and decided that the company shall be disciplined for misconduct and neglect that contravene relevant sections of the Lifts and Escalators Ordinance. ThyssenKrupp committed four disciplinary offences while being the contractor of the lift works at Selwyn Factory Building, Kwun Tong. It failed to ensure the works were carried out by two or more lift workers on four different occasions from April to September 2014, repeatedly contravening the requirement under section 4.11 of the Code of Practice for Lift Works and Escalator Works. The Disciplinary Board ordered ThyssenKrupp to pay a fine of \$180,000 and to pay the costs and expenses incurred in the proceedings totaling \$136,342. The Board's order was published in the Gazette on 22 July 2016.

Note 5a:

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 6/2017.

Note 5b:

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 9/2017.