

Quarterly Contractors' Performance Rating (CPR) of Registered Lift Contractors
(Assessment period: from January 2015 to December 2015) (Note 1)
(in alphabetical order based on the Services Quality Performance Rating)

| Name of Contractor | Contractor No. | Safety Performance Rating (Note 2) | Services Quality Performance Rating (Note 2) |
|---|----------------|------------------------------------|--|
| Anlev Elex Elevator Ltd. | RLC92004 | ★ | ★★★★★ |
| Antonfield Engineering Co., Ltd. | RLC95002 | ★ | ★★★★★ |
| Associated Engineers, Ltd. | RLC01003 | ★ | ★★★★★ |
| Association Electrical Engineering Limited | RLC02003 | ★ | ★★★★★ |
| Chun Ming Elevator Co. Ltd. | RLC93002 | ★ | ★★★★★ |
| Chun Ming Engineering Co. Ltd. | RLC88002 | ★ | ★★★★★ |
| CKP Building Service Systems Ltd. | RLC85001 | ★ | ★★★★★ |
| Elevator Parts Engineering Company Limited | RLC78001 | ★ | ★★★★★ |
| Hoi Fai Lift Engineering & Services Ltd. | RLC87006 | ★ | ★★★★★ |
| Hongkong International Terminals Limited | RLC01004 | ★ | ★★★★★ |
| Loedige Asia Limited | RLC07001 | ★ | ★★★★★ |
| Mitsubishi Elevator Hong Kong Company Limited | RLC88005 | ★ | ★★★★★ |
| Sun Fai Engineering & Equipment Co., Ltd. | RLC02002 | ★ | ★★★★★ |
| Taizoom Elevator Co.(H.K.)Ltd. | RLC10001 | ★ | ★★★★★ |
| Tak Lee Elevator Engineering Co., Ltd. | RLC02001 | ★ | ★★★★★ |
| Techfaith Engineering Limited | RLC00002 | ★ | ★★★★★ |

| | | | |
|---|----------|-------------|------|
| Chevalier (HK) Limited | RLC69001 | ★ | ★★★★ |
| Hitachi Elevator Engineering Co. (HK) Ltd. | RLC67001 | ★ | ★★★★ |
| Otis Elevator Company (HK) Limited | RLC75004 | ★ | ★★★★ |
| Schindler Lifts (Hong Kong) Ltd | RLC74002 | ★ | ★★★★ |
| Shan On Engineering Company Limited | RLC73002 | ★ | ★★★★ |
| The Express Lift Company Limited | RLC94001 | ★ | ★★★★ |
| ThyssenKrupp Elevator (HK) Limited (Note 3) | RLC96001 | ★ | ★★★★ |
| Toki Elevator Engineering Ltd. | RLC85002 | ★ | ★★★★ |
| Vertex Engineering Limited | RLC00001 | ★ | ★★★★ |
| Cheerwell Engineering Limited | RLC96002 | ★ | ★★ |
| Fujitec (HK) Co. Ltd. | RLC85005 | ★ | ★★ |
| Holake Hong Kong Lifts Ltd. | RLC80005 | ★ | ★★ |
| Rich Mark Engineering Limited | RLC99001 | ★ | ★ |
| Jekco Elevators Ltd. | RLC97001 | ★ | |
| Lighthouse Elevator Engineering Limited | RLC98003 | ★ | |
| Nikkin Lifts & Escalators Limited | RLC91002 | ★ | |
| Ring Hing Engineering Services Co., Ltd. | RLC97004 | ★ | |
| Sigma Elevator (HK) Ltd. | RLC04002 | ★ | |
| Ben Fung Machineries & Engineering Ltd | RLC73001 | (Note/註 4a) | |
| Eugene Engineering Co. Limited | RLC03002 | (Note/註 4b) | |
| KONE Elevator (HK) Ltd. | RLC87001 | (Note/註 4c) | |

Note 1:

The list of performance rating only shows the performance rating of the contractor who had five or more lifts being inspected by the EMSD during the assessment period. In other words, for those contractors having less than five lifts being inspected by the EMSD during the assessment period [refer to Table (a)], and contractors not undertaking any lift maintenance work during the assessment period [refer to Table (b)], their performances are not included in the list of performance rating.



(a) Contractors having less than five lifts being inspected by the EMSD during the assessment period:

| Name of Registered Lift Contractor | Contractor No. |
|------------------------------------|----------------|
| - | - |

(b) Contractors not undertaking any lift maintenance work during the assessment period:


| Name of Registered Lift Contractor | Contractor No. |
|------------------------------------|----------------|
| Holake (HK) Ltd. | RLC76001 |
| MTR Corporation Ltd. | RLC78003 |
| Ryoden Elevator Company Limited | RLC64001 |

Note 2:


| Rating | Description |
|---|--|
|  | No non-compliance found in both safety and services quality aspects in two recent quarterly announcements (Safety Star awarded and the services quality performance index at 100 points in the two recent quarterly announcements) |
|  | No non-compliance found in both safety and services quality aspects (performance index at 100 points in this quarterly announcement) |



No non-compliance found in safety aspect and service quality performance index is between 90 and 99 points



No non-compliance found in safety aspect and service quality performance index is between 80 and 89 points



No non-compliance found in safety aspect and service quality performance index is between 70 and 79 points



No non-compliance found in safety aspect and service quality performance index is less than 70 points

Note 3:

A lift incident happened on 8 October 2014 in an industrial building in Kwun Tong. The incident was caused by severe overload. During the investigation, the EMSD found that there were inadequacies in the maintenance works and working procedure of the lift contractor, ThyssenKrupp Elevator (HK) Limited. The EMSD is conducting a disciplinary inquiry into the case.

Note 4a:

Ben Fung Machineries & Engineering Ltd. (Ben Fung) was involved in a lift incident of over-travel during maintenance happened on 26 January 2014. The Court fined Ben Fung for \$ 3,000 on 14 January 2015 regarding her failure of inputting the lift fault information and the event details in the log book. The record of non-compliance will be kept for one year until 1/2016.

Note 4b:

Eugene Engineering Co. Limited (Eugene) was involved in an industrial incident during rope replacement happened on 5 August 2014. The Court fined Eugene for \$6,000 on 3 July 2015 regarding her failure to ensure that adequate safety precautions were taken. The record of non-compliance will be kept for one year until 7/2016.

Note 4c:

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 7/2016.