

Contractors' Performance Rating (CPR) of Registered Lift Contractor (From December 2010 to November 2011) (Note 1) (in performance index order)

| Name of Contractors | Contractor No. | No. of prosecution cases in the assessment period | No. of disciplinary cases in the assessment period | Previous Performance Index (September 2010 to August 2011) | December 2010 to November 2011 | | | | |
|---|----------------|---|--|--|---------------------------------|------------------------|----------------------------|-----------------------|-------------------|
| | | | | | Cumulated Maintenance PM Points | No. of Lifts Inspected | Maintenance Index (Note 2) | Safety Index (Note 2) | Performance Index |
| Antonfield Engineering Co., Ltd. | RLC95002 | | | 92 | 0 | 19 | 50 | 50 | 100 |
| Associated Engineers, Ltd. | RLC01003 | | | 100 | 0 | 7 | 50 | 50 | 100 |
| Association Electrical Engineering Limited | RLC02003 | | | 100 | 0 | 24 | 50 | 50 | 100 |
| Ben Fung Machineries & Engineering Ltd | RLC73001 | | | 100 | 0 | 36 | 50 | 50 | 100 |
| Cheerwell Engineering Limited | RLC96002 | | | 100 | 0 | 11 | 50 | 50 | 100 |
| Hoi Fai Lift Engineering & Services Ltd. | RLC87006 | | | 100 | 0 | 11 | 50 | 50 | 100 |
| Hongkong International Terminals Limited | RLC01004 | | | 100 | 0 | 17 | 50 | 50 | 100 |
| Ryoden Lift Services Limited | RLC99002 | | | 81 | 0 | 30 | 50 | 50 | 100 |
| Sun Fai Engineering & Equipment Co., Ltd. | RLC02002 | | | 63 | 0 | 13 | 50 | 50 | 100 |
| Vertex Engineering Limited | RLC00001 | | | 100 | 0 | 13 | 50 | 50 | 100 |
| Mitsubishi Elevator Hong Kong Company Limited | RLC88005 | | | 99 | 6 | 476 | 49 | 50 | 99 |
| Chevalier (HK) Limited | RLC69001 | | | 97 | 10 | 366 | 49 | 50 | 99 |
| Fujitec (HK) Co. Ltd. | RLC85005 | | | 92 | 10 | 364 | 49 | 50 | 99 |
| Rich Mark Engineering Limited | RLC99001 | | | 97 | 3 | 66 | 48 | 50 | 98 |
| Holake Hong Kong Lifts Ltd. | RLC80005 | | | 90 | 14 | 176 | 46 | 50 | 96 |
| Chun Ming Engineering Co. Ltd. | RLC88002 | | 1 | 96 | 8 | 87 | 45 | 50 | 95 |
| Shan On Engineering Company Limited | RLC73002 | | | 95 | 6 | 65 | 45 | 50 | 95 |
| Anlev Elex Elevator Ltd. | RLC92004 | | | 86 | 6 | 45 | 43 | 50 | 93 |
| Eugene Engineering Co. Limited | RLC03002 | | | 93 | 4 | 29 | 43 | 50 | 93 |
| KONE Elevator (HK) Ltd. | RLC87001 | | | 90 | 38 | 242 | 42 | 50 | 92 |
| Schindler Lifts (Hong Kong) Ltd | RLC74002 | | | 90 | 79 | 461 | 41 | 50 | 91 |
| Elevator Parts Engineering Company Limited | RLC78001 | | | 74 | 6 | 30 | 40 | 50 | 90 |
| Chun Ming Elevator Co. Ltd. | RLC93002 | 1 | | 78 | 8 | 36 | 39 | 50 | 89 |
| Otis Elevator Company (HK) Limited | RLC75004 | 2 | | 83 | 164 | 602 | 36 | 50 | 86 |
| The Express Lift Company Limited | RLC94001 | | | 92 | 40 | 132 | 35 | 50 | 85 |
| Hitachi Elevator Engineering Co. (HK) Ltd. | RLC67001 | | | 81 | 6 | 118 | 47 | 35 | 82 |
| Sigma Elevator (HK) Ltd. | RLC04002 | | | 70 | 32 | 81 | 30 | 50 | 80 |
| ThyssenKrupp Elevator (HK) Limited | RLC96001 | | 1 | 94 | 66 | 123 | 23 | 50 | 73 |
| Jekco Elevators Ltd. | RLC97001 | | | 71 | 16 | 29 | 22 | 50 | 72 |
| Toki Elevator Engineering Ltd. | RLC85002 | | | 72 | 23 | 40 | 21 | 50 | 71 |
| Lighthouse Elevator Engineering Limited | RLC98003 | | | 56 | 48 | 81 | 20 | 50 | 70 |
| CKP Building Service Systems Ltd. | RLC85001 | | | 50 | 6 | 10 | 20 | 50 | 70 |
| Shineford Engineering Limited | RLC97002 | | | 100 | 12 | 14 | 7 | 50 | 57 |
| Nikkin Lifts & Escalators Limited | RLC91002 | | | 77 | 90 | 242 | 31 | 20 | 51 |
| Ring Hing Engineering Services Co., Ltd. | RLC97004 | | | 83 | 61 | 55 | 0 | 50 | 50 |
| Techfaith Engineering Limited | RLC00002 | | | 50 | 40 | 9 | 0 | 50 | 50 |

Note 1 : For a better reflection of the contractors' performance in the assessment period, only the CPR results of Contractors whose installations have been inspected by EMSD for 5 times or more will be included in the table. It does not include (a) the contractors whose installations inspected by EMSD are less than 5 times and (b) contractors who do not undertake any lift maintenance work during the assessment period.

(a) Contractors whose installations have been inspected by EMSD were less than 5 times during the assessment period

| Name of Registered Lift Contractor | Contractor No. |
|--|----------------|
| Amanti (HK) Lift & Escalator Engineering Limited | RLC03001 |
| Loedige Asia Limited | RLC07001 |
| Taizoom Elevator Company (H.K.) Limited | RLC10001 |
| Tak Lee Elevator Engineering Co., Ltd. | RLC02001 |

(b) Contractors who did not undertake any lift maintenance work during the assessment period

| Name of Registered Lift Contractor | Contractor No. |
|--------------------------------------|----------------|
| Group Creation International Limited | RLC04001 |
| Holake (HK) Ltd. | RLC76001 |
| MTR Corporation Ltd. | RLC78003 |
| Ryoden Elevator Company Limited | RLC64001 |
| Whole Safe Ltd. | RLC92001 |

Note 2 : Performance Index (Full mark of 100) = Maintenance Index (0 to 50 marks) + Safety Index (0 to 50 marks); Maintenance Index = 50 x (1 - cumulated maintenance performance monitoring points / number of inspections in the period); Safety Index = 50 - cumulated safety performance monitoring points (each critical safety non-compliant item with 15 Points). The cumulated performance monitoring points are valid for 12 months. Details of the maintenance and safety items can be observed from http://www.emsd.gov.hk/emsd/e_download/pps/circular/A3/2_2011.pdf.