

Lift Equipment Failure Incident reported to EMSD (April 2025 to March 2026)

Contractor No.	Name of Contractor	Incident Date	Location	Incident Nature
RLC74002	Schindler Lifts (Hong Kong) Ltd.	01/04/2025	Cheung Fat Estate, Tsing Yi, N. T.	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component
RLC85005	Fujitec (HK) Co., Ltd.	14/05/2025	Faormont House, 8 Cotton Tree Drive, Central, Hong Kong.	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component
RLC74002	Schindler Lifts (Hong Kong) Ltd.	15/05/2025	Queen Mary Hospital Main Block, 102 Pok Fu Lam Road, Po Fu Lam, Hong Kong.	Passenger felt unwell after being trapped due to a malfunction of an electrical component.
RLC92004	Anlev Elex Elevator Ltd.	16/07/2025	Clinical Block 1, Queen Mary Hospital, 102 Pokfulam Road, Pok Fu Lam, Hong Kong.	Passenger felt unwell after being trapped due to a malfunction of an electrical component at lift pit.
RLC75004	Otis Elevator Company (H.K.) Ltd.	30/07/2025	Southsky, 80 Old Main Street, Aberdeen, Hong Kong	Passenger felt unwell after being trapped due to a malfunction of an electrical component.
RLC85005	Fujitec (HK) Co., Ltd.	03/08/2025	Blessings Garden Phase II, 56-58 Conduit Road, Mid-Levels, Hong Kong	Passenger tripping due to levelling difference of lift car at landing arisen from levelling device malfunction.
RLC80005	Holake Hong Kong Lifts Ltd.	16/08/2025	Harbour Heights, Tower 1-4, North Point, Hong Kong	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component
RLC88002	Chun Ming Engineering Co. Ltd.	12/09/2025	Modern Terminal Ltd., Berth One, Kwai Chung, N.T.	Passenger tripping due to levelling difference of lift car at landing arisen from poor landing contact.
RLC85005	Fujitec (HK) Co., Ltd.	17/09/2025	Sea Crest Village Phase 3, 18 Castle Peak Road, Sham Tseng, N.T.	Passenger tripping due to levelling difference of lift car at landing arisen from deviation of the working voltage of a PCB.
RLC87001	KONE Elevator (HK) Ltd.	28/09/2025	MTR Corporation, Jordan Station, Jordan, Kowloon	Passenger trapping due to a malfunction of an lift component.
RLC98003	Lighthouse Elevator Engineering Ltd.	31/10/2025	Pak Hoo Mansion, 554-560 Queen's Road West, Sai Ying Pun, Hong Kong	Passenger tripping due to levelling difference of lift car at landing arisen from poor landing contact.
RLC92004	Anlev Elex Elevator Ltd.	03/11/2025	Clinical Block 1, Queen Mary Hospital, 102 Pokfulam Road, Pok Fu Lam, Hong Kong.	Passenger felt unwell after being trapped due to a malfunction of an electrical component.
RLC74002	Schindler Lifts (Hong Kong) Ltd.	14/11/2025	Riviera Gardens, 28 Wing Shun Street, Tsuen Wan, N.T.	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component
RLC92004	Anlev Elex Elevator Ltd.	09/12/2025	Clinical Block 1, Queen Mary Hospital, 102 Pokfulam Road, Pok Fu Lam, Hong Kong.	Passenger felt unwell after being trapped due to a malfunction of an electrical component.
RLC92004	Anlev Elex Elevator Ltd.	12/01/2026	Clinical Block 1, Queen Mary Hospital, 102 Pokfulam Road, Pok Fu Lam, Hong Kong.	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component
RLC75004	Otis Elevator Company (H.K.) Ltd.	18/01/2026	Lok Shun House, Tsz Lok Estate, Tsz Wan Shan, Kowloon	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component
RLC92004	Anlev Elex Elevator Ltd.	21/01/2026	Clinical Block 1, Queen Mary Hospital, 102 Pokfulam Road, Pok Fu Lam, Hong Kong.	Passenger felt unwell after being trapped due to a malfunction of an electrical component.
RLC92004	Anlev Elex Elevator Ltd.	26/01/2026	Clinical Block 1, Queen Mary Hospital, 102 Pokfulam Road, Pok Fu Lam, Hong Kong.	Passenger trapping due to a malfunction of an lift component.
RLC92004	Anlev Elex Elevator Ltd.	26/01/2026	Clinical Block 1, Queen Mary Hospital, 102 Pokfulam Road, Pok Fu Lam, Hong Kong.	Passenger trapping due to a malfunction of an lift component.
RLC96001	TK Elevator (HK) Limited	04/02/2026	Central station of MTRC, Chater Road, Central, Hong Kong	Passenger felt unwell after being trapped due to a malfunction of a mechanical component.
RLC80005	Holake Hong Kong Lifts Ltd.	16/02/2026	Tung Fat House, 306-310 Sai Yeung Choi Street North, Mong Kok, Kowloon	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component
RLC74002	Schindler Lifts (Hong Kong) Ltd.	23/02/2026	Discovery Park, 398 Castle Peak Road, Tsuen Wan, N.T.	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component
RLC69001	CHEVALIER (HK) LTD.	23/02/2026	Sai Kung Town Centre, 22-40 Fuk Man Road, Sai Kung, N.T.	Levelling difference of lift car at landing arisen from malfunction of electrical component

