

Escalator Equipment Failure Incident reported to EMSD (Jan 2021 to Jun 2021)

Contractor No.	Name of Contractor	Incident Date	Location	Incident Nature
REC80001	Holake Hong Kong Lifts Ltd.	26/01/2021	Citiplaza Stage VA, Taikoo Shing Road, Tai Koo Shing, Hong Kong	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC87001	KONE Elevator (HK) Ltd.	31/01/2021	Tuen Mun Town Plaza, 1 Tuen Shun Street , Tuen Mun, N.T.	Protruded steel wire from the skirt brush deflector of an escalator resulting in passenger injury.
REC75003	Otis Elevator Company (HK) Ltd.	31/01/2021	Metroplaza, 223 Hing Fong Road, Kwai Chung, N.T.	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC74002	Schindler Lifts (HK) Ltd.	22/02/2021	Chi Fu Landmark, Chi Fu Fa Yuen, Pok Fu Lam Road, Pok Fu Lam, Hong Kong	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC85004	Fujitec (HK) Co., Ltd.	22/02/2021	MOSTown, 18 On Luk Street, Ma On Shan, N.T.	Protruded steel wire from the surface of the handrail of an escalator resulting in passenger injury.
REC75003	Otis Elevator Company (HK) Ltd.	22/03/2021	MTR Corporation, Kam Sheung Road Station, Yuen Long, N.T.	Burning smell from brake mechanism due to malfunction of electrical component and caused brake engaged while the escalator continues running.

No. of Equipment Failure Records = 6