

Contractors' Performance Rating (CPR) of Registered Escalator Contractor (From June 2011 to August 2011) (Note 1) (in alphabetical order)

| Name of Registered Escalator Contractor | Contractor No. | No. of prosecution cases in the assessment period | No. of disciplinary cases in the assessment period | June 2011 to August 2011 | | | | |
|---|----------------|---|--|---------------------------------|-----------------------------|----------------------------|-----------------------|-------------------|
| | | | | Cumulated Maintenance PM Points | No. of Escalators Inspected | Maintenance Index (Note 2) | Safety Index (Note 2) | Performance Index |
| Anlev Elex Elevator Ltd. | REC92003 | | | 0 | 13 | 50 | 35 | 85 |
| Chevalier (HK) Limited | REC69001 | | | 0 | 29 | 50 | 50 | 100 |
| Eugene Engineering Co. Limited | REC03002 | | | 0 | 6 | 50 | 50 | 100 |
| Fujitec (HK) Co. Ltd. | REC85004 | | | 0 | 15 | 50 | 50 | 100 |
| Hitachi Elevator Engineering Co. (HK) Ltd. | REC67001 | | | 0 | 9 | 50 | 50 | 100 |
| Holake Hong Kong Lifts Ltd. | REC80001 | | | 0 | 13 | 50 | 50 | 100 |
| KONE Elevator (HK) Ltd. | REC87001 | | | 6 | 22 | 36 | 50 | 86 |
| Mitsubishi Elevator Hong Kong Company Limited | REC88002 | | | 0 | 39 | 50 | 50 | 100 |
| Nikken Lifts & Escalators Limited | REC91002 | | | 0 | 6 | 50 | 50 | 100 |
| Otis Elevator Company (HK) Limited | REC75003 | | | 6 | 27 | 39 | 50 | 89 |
| Schindler Lifts (Hong Kong) Ltd | REC74002 | | | 0 | 39 | 50 | 50 | 100 |
| Shineford Engineering Limited | REC20002 | | | 0 | 8 | 50 | 50 | 100 |
| Sigma Elevator (HK) Ltd. | REC04001 | | | 0 | 6 | 50 | 50 | 100 |
| The Express Lift Company Limited | REC94001 | | | 0 | 7 | 50 | 50 | 100 |
| ThyssenKrupp Elevator (HK) Limited | REC96001 | | | 0 | 11 | 50 | 50 | 100 |

| | |
|----------|--|
| Note 1 : | For better reflection of the contractors' performance in the assessment period, only the CPR results of Contractors whose installations inspected by EMSD for 5 times or more will be included in the table. It does not include (a) the contractors whose installations inspected by EMSD are less than 5 times and (b) contractors who do not undertake any escalator maintenance work during the assessment period. |
|----------|--|

(a) Contractors whose installations inspected by EMSD were less than 5 times during the assessment period

| Name of Registered Escalator Contractor | Contractor No. |
|--|----------------|
| Amanti (HK) Lift & Escalator Engineering Limited | REC03001 |
| Antonfield Engineering Co., Ltd. | REC95003 |
| Association Electrical Engineering Limited | REC04002 |
| Ben Fung Machineries & Engineering Ltd | REC01002 |
| Cheerwell Engineering Limited | REC05001 |
| CKP Building Service Systems Ltd. | REC99005 |
| CNIM Hong Kong Ltd | REC85001 |
| Chun Ming Engineering Co. Ltd. | REC88001 |
| Elevator Parts Engineering Company Limited | REC87005 |
| Jekco Elevators Ltd. | REC97001 |
| Rich Mark Engineering Limited | REC99001 |
| Ryoden Lift Services Ltd. | REC99002 |
| Sun Fai Engineering & Equipment Co., Ltd. | REC02001 |
| Techfaith Engineering Limited | REC00001 |

(b) Contractors who did not undertake any escalator maintenance work during the assessment period

| Name of Registered Escalator Contractor | Contractor No. |
|---|----------------|
| Holake (HK) Ltd. | REC79001 |
| MTR Corporation Ltd. | REC78002 |
| Ryoden Elevator Company Limited | REC64001 |
| Shan On Engineering Co. Ltd. | REC73002 |

| | |
|----------|---|
| Note 2 : | Performance Index (Full mark of 100) = Maintenance Index (0 to 50 marks) + Safety Index (0 to 50 marks); Maintenance Index = 50 x (1 - cumulated maintenance performance monitoring points / number of inspections in the period); Safety Index = 50 - cumulated safety performance monitoring points (each critical safety non-compliant item with 15 Points). The cumulated performance monitoring points are valid for 12 months. Details of the maintenance and safety items can be observed from http://www.emsd.gov.hk/emsd/e_download/pps/circular/A3/2_2011.pdf . |
|----------|---|