

## Reported Equipment Failure of Lift Incident to EMSD of 2009

Contractor No.	Name of Contractor	Incident Date	Location	Incident Nature
RLC04002	Sigma Elevator (HK) Limited	05/01/09	Lai Sun Commercial Centre, Cheung Sha Wan Road	Passenger entrapment due to defective control equipment
RLC04002		21/04/09	38 Hau Wo Street, Kennedy Town	Passenger entrapment due to defective car door component
RLC04002		06/05/09	Block 4, Jubilee Garden, Fo Tan	Passenger entrapment due to defective car door component
RLC04002		04/06/09	Block 2 Lok Hin Terrace, Chai Wan	Passenger loss of balance due to malfunction of the position detectors
RLC04002		14/07/09	Block 4, Jubilee Garden, Fo Tan, Shatin	Suspension of lift service due to instability of control equipment
RLC04002		21/11/09	Shing Yin House, Tin Shing Court, Tin Shui Wau	Passenger entrapment due to activation of the governor pulley switch
RLC67001	Hitachi Elevator Engg. Co. (HK) Ltd.	18/02/09	World Commercial Centre, Phase 1, Harbour City, Kowloon	Fire due to defective electrical component
RLC67001		03/03/09	Block A, Pearl City Mansion, Peterson Street, Causeway Bay	Passenger loss of balance due to instability of leveling control device
RLC69001	Chevalier (HK) Ltd.	15/01/09	Millennium City 1, KwunTong	Passenger entrapment due to activation of the compensation rope limit switch
RLC69001		17/02/09	Block 7, Braemar Hill Mansions, 43 Braemar Hill Road North Point	Passenger entrapment due to defective floor selection device
RLC69001		18/02/09	Sung Kee Factory Building, 18 Kwai Ting Road, Kwai Chung	Passenger entrapment due to damaged car door sill
RLC69001		28/04/09	Block E, Amoy Gardens, Ngau Tau Kok	Passenger entrapment due to defective floor selector
RLC69001		31/10/09	Block B1, Kornhill, Quarry Bay	Passenger loss of balance due to instability of car door component
RLC74002	Schindler Lifts (HK) Ltd.	12/03/09	Westlands Centre, 20 Westlands Road, Quarry Bay	Suspension rope pulled out of the socket termination
RLC74002		11/04/09	Luk Yeung Galleria (Shopping Centre), Tsuen Wan	Passenger entrapment due to defective car door component
RLC75004	Otis Elevator Co. (HK) Ltd.	02/12/08	Yuk On House, Kam On Court, Ma On Shan	Passenger entrapment due to defective motor equipment
RLC75004		11/01/09	Heng Shan House, Heng On Estate, Ma On Shan	Passenger entrapment due to broken suspension ropes
RLC75004		25/02/09	Heng Sing House, Heng On Estate, Ma On Shan	Poor contact of lift car position and call registration devices
RLC75004		05/05/09	Hing On House, Sui Wo Court, Fo Tan	Passenger entrapment due to defective control equipment
RLC75004		11/09/09	Concordia Plaza, Tsim Sha Tsui	Passenger loss of balance due to defective leveling control device
RLC75004		20/09/09	Tung Yat House, Lei Tung Estate, Apleichau	Passenger loss of balance due to defective leveling control device
RLC75004		29/10/09	Sun Hung Kai Centre, 30 Harbour Road, Wanchai	Passenger injury due to defective electrical component
RLC78001		Elevator Parts Engg. Co. Ltd.	30/03/09	Capital Commercial Building, 446-448 Shanghai Street
RLC80005	Holake Hong Kong Lifts Ltd.	09/03/09	Granville Building, 14 Granville Road, Tsim Sha Tsui	Passenger loss of balance due to instability of leveling control device
RLC85005	Fujitec (HK) Co. Ltd.	26/01/09	Block 1, Heng Fa Chuen, Chai Wan	Passenger loss of balance due to instability of leveling control device
RLC85005		06/06/09	Lung Fung Garden Car Park, Sheung Shui	Fire due to defective electrical component
RLC85005		31/08/09	Houston Centre, 63 Mody Road, Tsimshatsui East	Fire due to defective electrical component
RLC85005		17/11/09	Block 1, Tai Ping Industrial Centre, Tai Po	Wear and tear of the governor rope
RLC87001	KONE Elevator (H.K.) Ltd.	21/12/08	Tai Tung House, Tung Tau (II) Estate, Wong Tai Sin	Passenger loss of balance due to instability of leveling control device
RLC87001		11/01/09	Fu Shing House, Fung Shing Court, Shatin	Passenger loss of balance due to instability of leveling control device
RLC87001		13/01/09	Lung Cheung House, Lung Poon Court, Diamond Hill	Passenger entrapment due to defective compensation ropes
RLC87001		09/04/09	Metro Centre Phase II, Lam Hing Street, Kowloon Bay	Passenger entrapment due to instability of control equipment
RLC87001		09/05/09	Tsim Sha Tsui Station, Tsuen Wan Rail Line	Passenger loss of balance due to defective control equipment
RLC87001		10/05/09	Park Avenue Tower, Moreton Terrace, Causeway Bay	Passenger injury due to dislocation of car ceiling decoration
RLC87001		18/10/09	Nga Tsui House, Lok Nga Court, Nga Tau Kok, Kowloon	Activated safety system due to defective control device
RLC87001		23/10/09	Hiu Shun House, Hiu Lai Court, Kwun Tong	Passenger loss of balance due to instability of leveling control device
RLC87001		26/10/09	Wan Hang House, Wan Tau Tong Estate, Tai Po	Passenger loss of balance due to instability of leveling control device
RLC88002	Chun Ming Engineering Co. Ltd.	20/06/09	Shui On Court, 1-3 Tai Yuen Street, Wanchai	Passenger entrapment due to instability of control equipment
RLC91002	Nikkin Lift & Escalator Services Ltd.	13/08/09	Pak Tat Mansion, 6 Nam King Street, Jordan, Kowloon	Fire due to defective electrical component
RLC94001	The Express Lift Company Limited	19/02/09	Hong Sang House, Kin Sang Estate, Tuen Mun	Passenger entrapment due to defective car door component
RLC95002	Antonfield Engg. Co. Ltd.	20/04/09	Yue Hwa Godown Building, 57-61 Wo Yi Hop Road, Kwai Chung	Fire due to defective electrical component
RLC98003	Lighthouse Elevator Engineering Limited	7/2/2009	Block 4, Phase 1, Tai Hing Garden, Tuen Mun	Passenger entrapment due to defective controlling device