

## Lift Equipment Failure Incident reported to EMSD (from January to December 2010)

Contractor No.	Name of Contractor	Incident Date	Location	Incident Nature
RLC04002	Sigma Elevator (HK) Ltd.	15/03/10	Kam Dat House, Kam Ying Court, Ma On Shan	Motor equipment damaged
		11/09/10	Tsui Lai Garden, Sheung Shui	Stoppage of lift service due to failure of the counterweight
RLC67001	Hitachi Elevator Engineering Co. (HK) Ltd.	08/03/10	Enterprise Square 5, Kowloon Bay	Passenger's loss balance due to defective levelling device
		06/08/10	World Finance Centre, South Tower, Harbour City, TST	Passenger's loss balance due to defective levelling device
RLC69001	Chevalier (HK) Limited	16/12/09	49 Village Road, Happy Valley	Vehicle damaged due to malfunction of the hydraulic component
		26/12/09	Shatin Galleria, Shatin	Fire due to defective electrical component
		15/03/10	Tak Yue Mansion, 4-6 Dock Street, Hung Hom	Fire due to defective electrical component
		02/12/10	Springfield Garden, 11 Yuen Chau Kok Street, Shatin	Stoppage of lift service due to damage of the selector
RLC74002	Schindler Lifts (Hong Kong) Ltd.	07/05/10	The Manhattan, 33 Tai Tam Road	Passenger's loss of balance due to defective levelling device
		20/05/10	Two Pacific Place Office Block Queensway	Passenger entrapment due to defective travel pulse transmitter
		14/07/10	Tai Shun House, 4 Hong Cheung Street, Sai Wan Ho	Stoppage of lift due to defective levelling device
		30/08/10	Ocean Building, 70-84 Shanghai Street, Kowloon	Passenger's loss of balance due to defective levelling device
		31/08/10	Taikoo Shing Cityplaza Two	Passenger's loss of balance due to defective levelling device
		07/10/10	Asia Orient Tower Place 33 Lockhart Road, WanChai	Passenger entrapment due to defective level sensor
RLC75004	Otis Elevator Company (HK) Limited	06/05/10	Heng Yuet House, Heng On Estate, Ma On Shan	Stoppage of lift due to defective wiring connection
		22/07/10	Shum Shui Po MTR Station	Stoppage of stairlift due to defective stabilizer bracket screw
RLC80005	Holake Hong Kong Lifts Ltd.	28/01/10	233 Fa Yuen Street Mong Kok	Passenger injury due to defective electrical component
		30/06/10	Regal Riverside Hotel, Tai Chung Kiu Road, Shatin	Stoppage of lift due to defective counterweight roller-guide
RLC85005	Fujitec (HK) Co. Ltd.	09/04/10	Winfield Building, 1-14 Ventris, Happy Valley	Passenger's loss balance due to defective levelling device
		16/06/10	HK Academy Medicine, 99 Wong Chuk Hang Road, Hong Kong	Passenger's loss balance due to slippery of the braking component
		28/09/10	Block 2, Heng Fa Chuen, Shing Tai Road, Chai Wan	Passenger entrapment due to defective position detector
RLC87001	KONE Elevator (HK) Ltd.	19/12/09	Tin Shui Estate Commercial Centre, Tin Shui Wai	Passenger entrapment due to defective guide shoe
		25/03/10	Fai Lam House, Tsui Lam Estate, Tseung Kwan O	Passenger's loss balance due to defective levelling device
		16/04/10	SKH Tsang Shiu Tin Secondary School, Wo Che Estate, Shatin	Passenger's loss balance due to defective levelling device
		26/05/10	Pok Hong Estate, Shatin	Passenger's loss balance due to broken guide shoe
		17/06/10	Tak Nga Court, Tai Po	Passenger entrapment due to worn out bearing of the governor pulley
		31/10/10	Fu Shin Estate Commercial Complex	Passenger entrapment due to defective slow down switch
RLC88005	Mitsubishi Elevator Hong Kong Company Limited	07/06/10	Eaton Hotel 380 Nathan Road, Jordan	Stoppage of lift service due to broken suspension ropes
RLC92004	Anlev Elex Elevator Ltd.	10/08/10	Pacific Trade Centre, Kowloon Bay	Passenger's loss of balance due to defective levelling sensor
RLC93002	Chun Ming Elevator Co. Ltd.	13/08/10	Block A, 608 Castle Peak Road, Sham Shui Po	Fire due to defective motor equipment
		09/09/10	Ka Ming Court, 688 Castle Peak Road, Shum Shui Po	Fire due to breakage of suspension rope
RLC94001	The Express Lift Company Limited	25/04/10	Po Foo Building, 1-5 Foo Ming Street, Causeway Bay	Passenger entrapment due to defective car door component
RLC95002	Antofield Engineering Co. Ltd	10/04/10	43 Dundas Street, Mong Kok	Motor equipment damaged
PLR96001	ThyssenKrupp Elevator (HK) Limited	17/07/10	Lai Ting House, Lai Yan Court, 278 Lai King Shan Road, Lai King	Fire due to defective electrical component
RLC97002	Shineford Engineering Limited	05/05/10	Golden Dragon Building, 77 Kung Lok Road, Kwun Tong	Fire due to defective electrical component