

List of Registered Lift Contractor's Warning Letters Issued (from December 2010 to November 2011)

Month	Contractor No.	Name of Contractor	Brief Content of Warning Letter
11/2011	RLC00002	Techfaith Engineering Limited	The moving average of the PM points has exceeded 4 points within 12-month interval.
10/2011	RLC93002	Chun Ming Elevator Co. Ltd.	Failure to carry out periodic lift examination and testing within 12-month interval according to sections 21 and 23 of the Lifts and Escalators (Safety) Ordinance.
10/2011	RLC88002	Chun Ming Engineering Co. Ltd.	Failure to carry out periodic lift examination and testing within 12-month interval according to sections 21 and 23 of the Lifts and Escalators (Safety) Ordinance.
9/2011	RLC91002	Nikkin Lifts & Escalators Limited	A total of 15 PM points for non-compliant items found in a single unit inspection.
9/2011	RLC91002	Nikkin Lifts & Escalators Limited	A total of 15 PM points for non-compliant items found in a single unit inspection.
7/2011	RLC74002	Schindler Lifts (Hong Kong) Ltd.	Use of a lift without a permit issued by the Director.
6/2011	RLC91002	Nikkin Lifts & Escalators Limited	A total of 12 PM points for non-compliant items found in a single unit inspection.
6/2011	RLC85005	Fujitec (HK) Co. Ltd.	Failure to carry out periodic lift examination and testing within 12-month interval according to sections 21 and 23 of the Lifts and Escalators (Safety) Ordinance.
6/2011	RLC88002	Chun Ming Engineering Co. Ltd.	Failure to carry out periodic lift examination and testing within 12-month interval according to sections 21 and 23 of the Lifts and Escalators (Safety) Ordinance.
6/2011	RLC67001	Hitachi Elevator Engineering Co. (HK) Ltd.	A total of 15 PM points for non-compliant items found in a single unit inspection.
5/2011	RLC75004	Otis Elevator Company (HK) Limited	Conviction by the court for contravening sections 11J(1) 、27G and 27H of the Lifts and Escalators (Safety) Ordinance.
5/2011	RLC91002	Nikkin Lifts & Escalators Limited	Failure to maintain a relay of the braking system in good condition.
2/2011	RLC74002	Schindler Lifts (Hong Kong) Ltd.	Failure to carry out periodic lift examination and testing within 12-month interval according to sections 21 and 23 of the Lifts and Escalators (Safety) Ordinance.
2/2011	RLC80005	Holake Hong Kong Lifts Ltd.	Failure to carry out periodic lift examination and testing within 12-month interval according to sections 21 and 23 of the Lifts and Escalators (Safety) Ordinance.