Quarterly Contractors' Performance Rating (CPR) of Registered Lift Contractors (Assessment period: from October 2016 to September 2017) (Note 1) (in alphabetical order based on the Services Quality Performance Rating)

Name of Contractor	Contractor No.	Safety Performance Rating ^(Note 2)	Services Quality Performance Rating (Note 2)
Anlev Elex Elevator Ltd.	RLC92004	*	****
Antonfield Engineering Co., Ltd.	RLC95002	*	****
Association Electrical Engineering Limited	RLC02003	*	****
Associated Engineers, Ltd.	RLC01003	*	****
Ben Fung Machineries & Engineering Ltd	RLC73001	*	****
Cheerwell Engineering Limited	RLC96002	*	****
CKP Building Service Systems Ltd.	RLC85001	*	****
Elevator Parts Engineering Company Limited	RLC78001	*	****
Fujitec (HK) Co. Ltd.	RLC85005	*	****
Hoi Fai Lift Engineering & Services Ltd.	RLC87006	*	****
Hongkong International Terminals Limited	RLC01004	*	****
Loedige Asia Limited	RLC07001	*	****
Sun Fai Engineering & Equipment Co., Ltd.	RLC02002	*	****
Tak Lee Elevator Engineering Co., Ltd.	RLC02001	*	****
Techfaith Engineering Limited	RLC00002	*	****
Toki Elevator Engineering Ltd.	RLC85002	*	****
Vertex Engineering Limited	RLC00001	*	****

Chun Ming Engineering Co. Ltd.	RLC88002	*	***
German Edunburgh Elevator & Escalator (HK) Ltd.	RLC17001	*	****
Holake (HK) Ltd.	RLC76001	*	****
Jekco Elevators Ltd.	RLC97001	*	****
KONE Elevator (HK) Ltd.	RLC87001	*	****
Lighthouse Elevator Engineering Limited	RLC98003	*	***
Eugene Engineering Co. Limited	RLC03002	*	***
Hitachi Elevator Engineering Co. (HK) Ltd.	RLC67001	*	***
Holake Hong Kong Lifts Ltd.	RLC80005	*	***
Mitsubishi Elevator Hong Kong Company Limited	RLC88005	*	***
Nikkin Lifts & Escalators Limited	RLC91002	*	***
Ring Hing Engineering Services Co., Ltd.	RLC97004	*	***
Schindler Lifts (Hong Kong) Ltd.	RLC74002	*	***
Sigma Elevator (HK) Ltd.	RLC04002	*	***
ThyssenKrupp Elevator (HK) Limited	RLC96001	*	***
Shan On Engineering Company Limited	RLC73002	*	**
The Express Lift Company Limited	RLC94001	*	**
Chun Ming Elevator Co. Ltd.	RLC93002	*	*
Rich Mark Engineering Limited	RLC99001	*	*
Taizoom Elevator Co.(H.K.)Ltd.	RLC10001	*	
Chevalier (HK) Limited	RLC69001	(Note/註 3a)	

Note 1:

The list of performance rating only shows the performance rating of the contractor who had five or more lifts being inspected by the EMSD during the assessment period. In other words, for those contractors having less than five lifts being inspected by the EMSD during the assessment period [refer to Table (a)], and contractors not undertaking any lift maintenance work during the assessment period [refer to Table (b)], their performances are not included in the list of performance rating.

(a) Contractors having less than five lifts being inspected by the EMSD during the assessment period:

Name of Registered Lift Contractor	Contractor No.
-	-

(b) Contractors not undertaking any lift maintenance work during the assessment period:

Name of Registered Lift Contractor	Contractor No.
MTR Corporation Ltd.	RLC78003
Ryoden Elevator Company Limited	RLC64001

Note 2:

Rating	Description
* + ****	No non-compliance found in both safety and services quality aspects in two recent quarterly announcements (Safety Star awarded and the services quality performance index at 100 points in the two recent quarterly announcements)
* + ****	No non-compliance found in both safety and services quality aspects (performance index at 100 points in this quarterly announcement)

★ + ***	No non-compliance found in safety aspect and service quality performance index is between 90 and 99 points
★ + * *	No non-compliance found in safety aspect and service quality performance index is between 80 and 89 points
★ + ★	No non-compliance found in safety aspect and service quality performance index is between 70 and 79 points
*	No non-compliance found in safety aspect and service quality performance index is less than 70 points

Note 3a:

Non-compliances found in safety aspect, thus served with two warning letters. The records of non-compliance will be kept for one year until 3/2018 and 6/2018 respectively.

Note 3b:

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 3/2018.