

Quarterly Contractors' Performance Rating (CPR) of Registered Lift Contractors  
(Assessment period: from July 2016 to June 2017) (Note 1)  
(in alphabetical order based on the Services Quality Performance Rating)

Name of Contractor	Contractor No.	Safety Performance Rating (Note 2)	Services Quality Performance Rating (Note 2)
Anlev Elex Elevator Ltd.	RLC92004	★	★★★★★
Antonfield Engineering Co., Ltd. (Note 3)	RLC95002	★	★★★★★
Association Electrical Engineering Limited	RLC02003	★	★★★★★
Associated Engineers, Ltd.	RLC01003	★	★★★★★
Ben Fung Machineries & Engineering Ltd	RLC73001	★	★★★★★
Cheerwell Engineering Limited	RLC96002	★	★★★★★
CKP Building Service Systems Ltd.	RLC85001	★	★★★★★
Elevator Parts Engineering Company Limited	RLC78001	★	★★★★★
Fujitec (HK) Co. Ltd.	RLC85005	★	★★★★★
Hoi Fai Lift Engineering & Services Ltd.	RLC87006	★	★★★★★
Hongkong International Terminals Limited	RLC01004	★	★★★★★
Loedige Asia Limited	RLC07001	★	★★★★★
Sun Fai Engineering & Equipment Co., Ltd.	RLC02002	★	★★★★★
Tak Lee Elevator Engineering Co., Ltd.	RLC02001	★	★★★★★
Toki Elevator Engineering Ltd.	RLC85002	★	★★★★★
Vertex Engineering Limited	RLC00001	★	★★★★★

---

Techfaith Engineering Limited	RLC00002	★	★★★★★
Chun Ming Engineering Co. Ltd.	RLC88002	★	★★★
Hitachi Elevator Engineering Co. (HK) Ltd.	RLC67001	★	★★★
Holake Hong Kong Lifts Ltd.	RLC80005	★	★★★
KONE Elevator (HK) Ltd.	RLC87001	★	★★★
Mitsubishi Elevator Hong Kong Company Limited	RLC88005	★	★★★
Nikkin Lifts & Escalators Limited	RLC91002	★	★★★
Rich Mark Engineering Limited	RLC99001	★	★★★
Ring Hing Engineering Services Co., Ltd.	RLC97004	★	★★★
Schindler Lifts (Hong Kong) Ltd.	RLC74002	★	★★★
The Express Lift Company Limited	RLC94001	★	★★★
ThyssenKrupp Elevator (HK) Limited	RLC96001	★	★★★
Jekco Elevators Ltd.	RLC97001	★	★★
Lighthouse Elevator Engineering Limited	RLC98003	★	★★
Shan On Engineering Company Limited	RLC73002	★	★★
Eugene Engineering Co. Limited	RLC03002	★	★
Chun Ming Elevator Co. Ltd.	RLC93002	★	
Taizoom Elevator Co.(H.K.)Ltd.	RLC10001	★	
Chevalier (HK) Limited	RLC69001	(Note/註 4a)	

---

Otis Elevator Company (HK) Limited      RLC75004      (Note/註 4b)

Sigma Elevator (HK) Ltd.      RLC04002      (Note/註 4c)

---

**Note 1:**

The list of performance rating only shows the performance rating of the contractor who had five or more lifts being inspected by the EMSD during the assessment period. In other words, for those contractors having less than five lifts being inspected by the EMSD during the assessment period [refer to Table (a)], and contractors not undertaking any lift maintenance work during the assessment period [refer to Table (b)], their performances are not included in the list of performance rating.


(a) Contractors having less than five lifts being inspected by the EMSD during the assessment period:






Name of Registered Lift Contractor	Contractor No.
-	-

(b) Contractors not undertaking any lift maintenance work during the assessment period:

Name of Registered Lift Contractor	Contractor No.
German Edunburgh Elevator & Escalator (HK) Ltd.	RLC17001
Holake (HK) Ltd.	RLC76001
MTR Corporation Ltd.	RLC78003
Ryoden Elevator Company Limited	RLC64001

**Note 2:**

Rating	Description
	No non-compliance found in both safety and services quality aspects in two recent quarterly announcements (Safety Star awarded and the services quality performance index at 100 points in the two recent quarterly announcements)

	No non-compliance found in both safety and services quality aspects (performance index at 100 points in this quarterly announcement)
	No non-compliance found in safety aspect and service quality performance index is between 90 and 99 points
	No non-compliance found in safety aspect and service quality performance index is between 80 and 89 points
	No non-compliance found in safety aspect and service quality performance index is between 70 and 79 points
	No non-compliance found in safety aspect and service quality performance index is less than 70 points

Note 3:

The Disciplinary Board has completed the disciplinary hearings on the performance of Antonfield Engineering Company Limited (Antonfield), and decided that the company should be disciplined for misconduct and neglect that contravened relevant sections of the Lifts and Escalators Ordinance (the Ordinance). Antonfield committed two disciplinary offences while being the contractor of the lift works at Wah Lee Building, Sai Ying Pun. It contravened sections 3(2)(a) and 3(4) of the Lifts and Escalators (General) Regulation and failed to establish a work system to ensure that the lift works were carried out in accordance with the provisions of the Ordinance. The Disciplinary Board ordered Antonfield to pay a fine of \$60,000 and the costs and expenses incurred in the proceedings totalling \$169,900. The Board's order was published in the Gazette on 2 June 2017. In view that Antonfield had been convicted by court in 2014 for contravention of sections 3(2)(a) and 3(4) of the Regulation, safety star and quality stars had not been awarded to Antonfield in the period from October 2014 to September 2015.

Note 4a:

Non-compliances found in safety aspect, thus served with two warning letters. The records of non-compliance will be kept for one year until 3/2018 and 6/2018 respectively.

Note 4b:

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 3/2018.

Note 4c:

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 9/2017.