

**Contractors' Performance Rating (CPR) of Registered Lift Contractors  
(From July 2012 to June 2013)  
(in alphabetical order)**

Name of Contractors	Contractor No.
<b>Category I: Those showing good performance with no non-compliances found in both safety and maintenance aspects</b>	
Antonfield Engineering Co., Ltd.	RLC95002
Association Electrical Engineering Limited	RLC02003
Ben Fung Machineries & Engineering Ltd	RLC73001
Cheerwell Engineering Limited	RLC96002
Chun Ming Engineering Co. Ltd.	RLC88002
CKP Building Service Systems Ltd.	RLC85001
Fujitec (HK) Co. Ltd.	RLC85005
Hitachi Elevator Engineering Co. (HK) Ltd.	RLC67001
Hongkong International Terminals Limited	RLC01004
Mitsubishi Elevator Hong Kong Company Limited	RLC88005
Rich Mark Engineering Limited	RLC99001
Shan On Engineering Company Limited	RLC73002
Sun Fai Engineering & Equipment Co., Ltd.	RLC02002
Techfaith Engineering Limited	RLC00002
ThyssenKrupp Elevator (HK) Limited	RLC96001
Toki Elevator Engineering Ltd.	RLC85002
Vertex Engineering Limited	RLC00001
<b>Category II: Those with no non-compliances found in safety aspect, but with room for improvement in maintenance aspect</b>	
Anlev Elex Elevator Ltd.	RLC92004
Chevalier (HK) Limited	RLC69001
Eugene Engineering Co. Limited	RLC03002
Holake Hong Kong Lifts Ltd.	RLC80005
Jekco Elevators Ltd.	RLC97001
KONE Elevator (HK) Ltd.	RLC87001
Lighthouse Elevator Engineering Limited	RLC98003
Nikkin Lifts & Escalators Limited	RLC91002
Otis Elevator Company (HK) Limited	RLC75004
Ring Hing Engineering Services Co., Ltd.	RLC97004
Schindler Lifts (Hong Kong) Ltd	RLC74002
Sigma Elevator (HK) Ltd.	RLC04002
Taizoom Elevator Co.(H.K.)Ltd.	RLC10001
The Express Lift Company Limited	RLC94001
<b>Category III: Those with non-compliances found in safety performance aspect, thus served with warning letter, and further investigation is in progress</b>	
Chun Ming Elevator Co. Ltd.	RLC88002
Elevator Parts Engineering Company Limited	RLC78001
Shineford Engineering Limited*	RLC97002

\* In view of a recent serious lift incident at North Point on 2 March 2013, the Registrar is satisfied that Shineford Engineering Limited (Shineford) contravened the Lifts and Escalators Ordinance (Chapter 618) by failing to ensure that the lift works were carried out properly and safely. The Registrar exercised the power to suspend the registration of Shineford as a registered lift contractor for six months, taking effect on 1 May 2013.

Note 1: For a better reflection of the contractors' performance in the assessment period, only the CPR results of Contractors whose installations have been inspected by EMSD for 5 times or more will be included in the table. It does not include (a) the contractors whose installations inspected by EMSD are less than 5 times and (b) contractors who do not undertake any escalator maintenance work during the assessment period.

- (a) Contractors whose installations have been inspected by EMSD were less than 5 times during the assessment period:

<b>Name of Registered Escalator Contractor</b>	<b>Contractor No.</b>
Amanti (HK) Lift & Escalator Engineering Limited	RLC03001
Associated Engineers, Ltd.	RLC01003
Hoi Fai Lift Engineering & Services Ltd.	RLC87006
Loedige Asia Limited	RLC07001
Tak Lee Elevator Engineering Co., Ltd.	RLC02001

- (b) Contractors who did not undertake any escalator maintenance work during the assessment period:

<b>Name of Registered Escalator Contractor</b>	<b>Contractor No.</b>
Group Creation International Limited	RLC04001
Holake (HK) Ltd.	RLC76001
MTR Corporation Ltd.	RLC78003
Ryoden Elevator Company Limited	RLC64001
Whole Safe Ltd.	RLC92001