

**Contractors' Performance Rating (CPR) of Registered Lift Contractors**  
**(From October 2012 to September 2013)**  
**(in alphabetical order)**

Name of Contractor	Contractor No.
<b>Category I: Those showing good performance with no non-compliances found in both safety and maintenance aspects</b>	
Anlev Elex Elevator Ltd.	RLC92004
Antonfield Engineering Co., Ltd.	RLC95002
Association Electrical Engineering Limited	RLC02003
Ben Fung Machineries & Engineering Ltd	RLC73001
Cheerwell Engineering Limited	RLC96002
Chun Ming Elevator Co. Ltd.	RLC93002
Chun Ming Engineering Co. Ltd.	RLC88002
CKP Building Service Systems Ltd.	RLC85001
Hitachi Elevator Engineering Co. (HK) Ltd.	RLC67001
Hongkong International Terminals Limited	RLC01004
Mitsubishi Elevator Hong Kong Company Limited	RLC88005
Rich Mark Engineering Limited	RLC99001
Shan On Engineering Company Limited	RLC73002
Sun Fai Engineering & Equipment Co., Ltd.	RLC02002
Techfaith Engineering Limited	RLC00002
ThyssenKrupp Elevator (HK) Limited	RLC96001
Toki Elevator Engineering Ltd.	RLC85002
Vertex Engineering Limited	RLC00001
<b>Category II: Those with no non-compliances found in safety aspect, but with room for improvement in maintenance aspect</b>	
Chevalier (HK) Limited	RLC69001
Eugene Engineering Co. Limited	RLC03002
Fujitec (HK) Co. Ltd.	RLC85005
Holake Hong Kong Lifts Ltd.	RLC80005
Jekco Elevators Ltd.	RLC97001
KONE Elevator (HK) Ltd.	RLC87001
Lighthouse Elevator Engineering Limited	RLC98003
Nikkin Lifts & Escalators Limited	RLC91002
Otis Elevator Company (HK) Limited	RLC75004

Ring Hing Engineering Services Co., Ltd.	RLC97004
Schindler Lifts (Hong Kong) Ltd	RLC74002
Sigma Elevator (HK) Ltd.	RLC04002
Taizoom Elevator Co.(H.K.)Ltd.	RLC10001
The Express Lift Company Limited	RLC94001
<b>Category III: Those with non-compliances found in safety performance aspect, thus served with warning letter, and further investigation is in progress</b>	
Elevator Parts Engineering Company Limited	RLC78001
Shineford Engineering Limited*	RLC97002

\* The registration as a registered lift contractor of Shineford Engineering Limited was cancelled on 16 October 2013.

Note 1: For a better reflection of the contractors' performance in the assessment period, only the CPR results of Contractors whose installations have been inspected by EMSD for 5 times or more will be included in the table.

It does not include (a) the contractors whose installations inspected by EMSD are less than 5 times and (b) contractors who do not undertake any escalator maintenance work during the assessment period.

a) Contractors whose installations have been inspected by EMSD were less than 5 times during the assessment period:

Name of Registered Lift Contractor	Contractor No.
Amanti (HK) Lift & Escalator Engineering Limited	RLC03001
Associated Engineers, Ltd.	RLC01003
Hoi Fai Lift Engineering & Services Ltd.	RLC87006
Loedige Asia Limited	RLC07001
Tak Lee Elevator Engineering Co., Ltd.	RLC02001

(b) Contractors who did not undertake any lift maintenance work during the assessment period:

Name of Registered Lift Contractor	Contractor No.
Group Creation International Limited	RLC04001
Holake (HK) Ltd.	RLC76001
MTR Corporation Ltd.	RLC78003
Ryoden Elevator Company Limited	RLC64001
Whole Safe Ltd.	RLC92001