

Registered Lift Contractors

Quarterly Contractors' Performance Rating (CPR) of Registered Lift Contractors

(Assessment period: from January 2013 to December 2013 ^(Note 1))

(in alphabetical order based on the Service Quality Performance Rating)

Please select and click the respective contractor name to access the contractor's related information

Name of Contractors	Contractor No.	Safety Performance Rating (Note 2)	Service Quality Performance Rating (Note 2)
Anlev Elex Elevator Ltd.	RLC92004	★	★★★★★
Antonfield Engineering Co., Ltd.	RLC95002	★	★★★★★
Associated Engineers, Ltd.	RLC01003	★	★★★★★
Association Electrical Engineering Limited	RLC02003	★	★★★★★
Ben Fung Machineries & Engineering Ltd	RLC73001	★	★★★★★
Cheerwell Engineering Limited	RLC96002	★	★★★★★
Chun Ming Elevator Co. Ltd.	RLC93002	★	★★★★★
Chun Ming Engineering Co. Ltd.	RLC88002	★	★★★★★
CKP Building Service Systems Ltd.	RLC85001	★	★★★★★
Hitachi Elevator Engineering Co. (HK) Ltd.	RLC67001	★	★★★★★
Hoi Fai Lift Engineering & Services Ltd.	RLC87006	★	★★★★★
Hongkong International Terminals Limited	RLC01004	★	★★★★★
Loedige Asia Limited	RLC07001	★	★★★★★
Mitsubishi Elevator Hong Kong Company Limited	RLC88005	★	★★★★★
Rich Mark Engineering Limited	RLC99001	★	★★★★★
Shan On Engineering Company Limited	RLC73002	★	★★★★★
Sun Fai Engineering & Equipment Co., Ltd.	RLC02002	★	★★★★★
Techfaith Engineering Limited	RLC00002	★	★★★★★
Toki Elevator Engineering Ltd.	RLC85002	★	★★★★★
Vertex Engineering Limited	RLC00001	★	★★★★★
Eugene Engineering Co. Limited	RLC03002	★	★★★★
Tak Lee Elevator Engineering Co., Ltd.	RLC02001	★	★★★★

The Express Lift Company Limited	RLC94001	★	★★★★★
Chevalier (HK) Limited	RLC69001	★	★★★★
Fujitec (HK) Co. Ltd. (Note 3)	RLC85005	★	★★★★
Jekco Elevators Ltd.	RLC97001	★	★★★★
KONE Elevator (HK) Ltd.	RLC87001	★	★★★★
Otis Elevator Company (HK) Limited	RLC75004	★	★★★★
Ring Hing Engineering Services Co., Ltd.	RLC97004	★	★★★★
Schindler Lifts (Hong Kong) Ltd	RLC74002	★	★★★★
Holake Hong Kong Lifts Ltd.	RLC80005	★	★★
Taizoom Elevator Co.(H.K.)Ltd.	RLC10001	★	★★
ThyssenKrupp Elevator (HK) Limited	RLC96001	★	★★
Nikkin Lifts & Escalators Limited	RLC91002	★	★
Sigma Elevator (HK) Ltd.	RLC04002	★	★
Lighthouse Elevator Engineering Limited	RLC98003	★	-
Amanti (HK) Lift & Escalator Engineering Limited	RLC03001		(Note/註 4a)
Elevator Parts Engineering Company Limited	RLC78001		(Note/註 4b)

Note 1:

The list of performance rating only shows the performance rating of the contractor who had five or more lifts being inspected by the EMSD during the assessment period. In other words, for those contractors having less than five lifts being inspected by the EMSD during the assessment period [refer to Table (a)], and the contractors who did not undertake any lift maintenance work during the assessment period [refer to Table (b)], their performance does not include in the list of performance rating.

(a) Contractors having less than five lifts being inspected by the EMSD during the assessment period:

Name of Registered Lift Contractor	Contractor No.
------------------------------------	----------------

(Nil)

(b) Contractors who did not undertake any lift maintenance work during the assessment period:

Name of Registered Lift Contractor	Contractor No.
------------------------------------	----------------

Group Creation International Limited	RLC04001
--------------------------------------	----------

Holake (HK) Ltd.	RLC76001
MTR Corporation Ltd.	RLC78003
Ryoden Elevator Company Limited	RLC64001
Whole Safe Ltd.	RLC92001

Note 2 :



No non-compliance found in both safety and services quality aspects in two recent quarterly announcements (Safety Star awarded and the services quality performance index at 100 points in the two recent quarterly announcements)



No non-compliance found in both safety and services quality aspects (performance index at 100 points in this quarterly announcement)



No non-compliance found in safety aspect and service quality performance index is between 90 and 99 points



No non-compliance found in safety aspect and service quality performance index is between 80 and 89 points



No non-compliance found in safety aspect and service quality performance index is between 70 and 79 points



No non-compliance found in safety aspect and service quality performance index is less than 70 points

Note 3 :

Fujitec (HK) Co. Ltd. was involved in a lift incident of suspension rope breakage happened in 13 January 2014. The incident is under investigation.

Note 4a :

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 12/2014.

Note 4b :

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 2/2014.