

## Registered Lift Contractors

### Quarterly Contractors' Performance Rating (CPR) of Registered Lift Contractors

(Assessment period: from April 2013 to March 2014 <sup>(Note 1)</sup>)

(in alphabetical order based on the Service Quality Performance Rating)

Name of Contractor	Contractor No.	Safety Performance	Services Quality
		Rating (Note 2)	Performance Rating (Note 2)
Anlev Elex Elevator Ltd.	RLC92004	★	★★★★★
Antonfield Engineering Co., Ltd. <sup>(Note 3)</sup>	RLC95002	★	★★★★★
Associated Engineers, Ltd.	RLC01003	★	★★★★★
Association Electrical Engineering Limited	RLC02003	★	★★★★★
Ben Fung Machineries & Engineering Ltd. <sup>(Note 4)</sup>	RLC73001	★	★★★★★
Cheerwell Engineering Limited	RLC96002	★	★★★★★
Chun Ming Elevator Co. Ltd.	RLC93002	★	★★★★★
CKP Building Service Systems Ltd.	RLC85001	★	★★★★★
Eugene Engineering Co. Limited	RLC03002	★	★★★★★
Hitachi Elevator Engineering Co. (HK) Ltd.	RLC67001	★	★★★★★
Hoi Fai Lift Engineering & Services Ltd.	RLC87006	★	★★★★★
Hongkong International Terminals Limited	RLC01004	★	★★★★★
Loedige Asia Limited	RLC07001	★	★★★★★
Mitsubishi Elevator Hong Kong Company Limited	RLC88005	★	★★★★★
Rich Mark Engineering Limited	RLC99001	★	★★★★★
Shan On Engineering Company Limited	RLC73002	★	★★★★★
Sun Fai Engineering & Equipment Co., Ltd.	RLC02002	★	★★★★★
Tak Lee Elevator Engineering Co., Ltd.	RLC02001	★	★★★★★
Techfaith Engineering Limited	RLC00002	★	★★★★★
The Express Lift Company Limited	RLC94001	★	★★★★★
Toki Elevator Engineering Ltd.	RLC85002	★	★★★★★
Vertex Engineering Limited	RLC00001	★	★★★★★
Elevator Parts Engineering Company Limited	RLC78001	★	★★★★
Jekco Elevators Ltd.	RLC97001	★	★★★★

Taizoom Elevator Co.(H.K.)Ltd.	RLC10001	★	★★★★★
Chevalier (HK) Limited	RLC69001	★	★★★★
Chun Ming Engineering Co. Ltd.	RLC88002	★	★★★★
Holake Hong Kong Lifts Ltd.	RLC80005	★	★★★★
KONE Elevator (HK) Ltd.	RLC87001	★	★★★★
Otis Elevator Company (HK) Limited	RLC75004	★	★★★★
Ring Hing Engineering Services Co., Ltd.	RLC97004	★	★★★★
Schindler Lifts (Hong Kong) Ltd	RLC74002	★	★★★★
Sigma Elevator (HK) Ltd.	RLC04002	★	★★
ThyssenKrupp Elevator (HK) Limited	RLC96001	★	★★
Nikkin Lifts & Escalators Limited	RLC91002	★	★
Lighthouse Elevator Engineering Limited	RLC98003	★	-
Amanti (HK) Lift & Escalator Engineering Limited	RLC03001		(Note/註 5a)
Fujitec (HK) Co. Ltd.	RLC85005		(Note/註 5b)

Note 1:

The list of performance rating only shows the performance rating of the contractor who had five or more lifts being inspected by the EMSD during the assessment period. In other words, for those contractors having less than five lifts being inspected by the EMSD during the assessment period [refer to Table (a)], and the contractors who did not undertake any lift maintenance work during the assessment period [refer to Table (b)], their performances are not included in the list of performance rating.

(a) Contractors having less than five lifts being inspected by the EMSD during the assessment period:

Name of Registered Lift Contractor	Contractor No.
Nil.	

(b) Contractors who did not undertake any lift maintenance work during the assessment period:

Name of Registered Lift Contractor	Contractor No.
Group Creation International Limited	RLC04001
Holake (HK) Ltd.	RLC76001
MTR Corporation Ltd.	RLC78003







Ryoden Elevator Company Limited

RLC64001

Whole Safe Ltd.

RLC92001

Note 2:

-  No non-compliance found in both safety and services quality aspects in two recent quarterly announcements (Safety Star awarded and the services quality performance index at 100 points in the two recent quarterly announcements)
-  No non-compliance found in both safety and services quality aspects (performance index at 100 points in this quarterly announcement)
-  No non-compliance found in safety aspect and service quality performance index is between 90 and 99 points
-  No non-compliance found in safety aspect and service quality performance index is between 80 and 89 points
-  No non-compliance found in safety aspect and service quality performance index is between 70 and 79 points
-  No non-compliance found in safety aspect and service quality performance index is less than 70 points

Note 3:

Antonfield Engineering Co., Ltd. was involved in carrying out a major alteration works on a lift without approval on 20 December 2012. The case is being heard in court.

Note 4:

Ben Fung Machineries & Engineering Ltd. was involved in a lift incident of over-travel during maintenance happened on 26 January 2014. The incident is under investigation.

Note 5a:

Non-compliance found in safety aspect of Amanti (HK) Lift & Escalator Engineering Limited, thus served with warning letter. The record of non-compliance will be kept for one year until 12/2014.

Note 5b:

Non-compliance found in safety aspect of Fujitec (HK) Co. Ltd., thus served with warning letter. The record of non-compliance will be kept for one year until 1/2015.