

Registered Lift Contractors

Quarterly Contractors' Performance Rating (CPR) of Registered Lift Contractors

(Assessment period: from October 2013 to September 2014) ^(Note 1)

(in alphabetical order based on the Services Quality Performance Rating)

Please select and click the respective contractor name to access the contractor's related information

Name of Contractor	Contractor No.	Safety Performance Rating (Note 2)	Services Quality Performance Rating (Note 2)
Anlev Elex Elevator Ltd.	RLC92004	★	★★★★★
Associated Engineers, Ltd.	RLC01003	★	★★★★★
Association Electrical Engineering Limited	RLC02003	★	★★★★★
Ben Fung Machineries & Engineering Ltd ^(Note 3)	RLC73001	★	★★★★★
Cheerwell Engineering Limited	RLC96002	★	★★★★★
Elevator Parts Engineering Company Limited	RLC78001	★	★★★★★
Eugene Engineering Co. Limited	RLC03002	★	★★★★★
Hoi Fai Lift Engineering & Services Ltd.	RLC87006	★	★★★★★
Hongkong International Terminals Limited	RLC01004	★	★★★★★
Jekco Elevators Ltd.	RLC97001	★	★★★★★
Loedige Asia Limited	RLC07001	★	★★★★★
Mitsubishi Elevator Hong Kong Company Limited	RLC88005	★	★★★★★
Rich Mark Engineering Limited	RLC99001	★	★★★★★
Shan On Engineering Company Limited	RLC73002	★	★★★★★
Sun Fai Engineering & Equipment Co., Ltd.	RLC02002	★	★★★★★
Taizoom Elevator Co.(H.K.)Ltd.	RLC10001	★	★★★★★
Tak Lee Elevator Engineering Co., Ltd.	RLC02001	★	★★★★★
Techfaith Engineering Limited	RLC00002	★	★★★★★
Toki Elevator Engineering Ltd.	RLC85002	★	★★★★★
Vertex Engineering Limited	RLC00001	★	★★★★★
Chevalier (HK) Limited	RLC69001	★	★★★★
Chun Ming Elevator Co. Ltd.	RLC93002	★	★★★★
Chun Ming Engineering Co. Ltd.	RLC88002	★	★★★★
CKP Building Service Systems Ltd.	RLC85001	★	★★★★

Name of Contractor	Contractor No.	Safety Performance Rating (Note 2)	Services Quality Performance Rating (Note 2)
Hitachi Elevator Engineering Co. (HK) Ltd.	RLC67001	★	★★★★
Holake Hong Kong Lifts Ltd.	RLC80005	★	★★★★
KONE Elevator (HK) Ltd.	RLC87001	★	★★★★
Ring Hing Engineering Services Co., Ltd.	RLC97004	★	★★★★
Sigma Elevator (HK) Ltd.	RLC04002	★	★★★★
The Express Lift Company Limited	RLC94001	★	★★★★
ThyssenKrupp Elevator (HK) Limited	RLC96001	★	★★★★
Lighthouse Elevator Engineering Limited	RLC98003	★	★★
Amanti (HK) Lift & Escalator Engineering Limited	RLC03001		(Note/註 4a)
Antonfield Engineering Co., Ltd.	RLC95002		(Note/註 4b)
Fujitec (HK) Co. Ltd.	RLC85005		(Note/註 4c)
Nikkin Lifts & Escalators Limited	RLC91002		(Note/註 4d)
Otis Elevator Company (HK) Limited	RLC75004		(Note/註 4e)
Schindler Lifts (Hong Kong) Ltd	RLC74002		(Note/註 4f)

Note 1:

The list of performance rating only shows the performance rating of the contractor who had five or more lifts being inspected by the EMSD during the assessment period. In other words, for those contractors having less than five lifts being inspected by the EMSD during the assessment period [refer to Table (a)], and contractors not undertaking any lift maintenance work during the assessment period [refer to Table (b)], their performances are not included in the list of performance rating.


(a) Contractors having less than five lifts being inspected by the EMSD during the assessment period:


Name of Registered Lift Contractor	Contractor No.
Ryoden Elevator Company Limited	RLC64001


(b) Contractors not undertaking any lift maintenance work during the assessment period:


Name of Registered Lift Contractor	Contractor No.
Group Creation International Limited	RLC04001
Holake (HK) Ltd.	RLC76001
MTR Corporation Ltd.	RLC78003
Whole Safe Ltd.	RLC92001


Note 2:


 No non-compliance found in both safety and services quality aspects in two recent quarterly announcements (Safety Star awarded and the services quality performance index at 100 points in the two recent quarterly announcements)

 No non-compliance found in both safety and services quality aspects (performance index at 100 points in this quarterly announcement)

 No non-compliance found in safety aspect and service quality performance index is between 90 and 99 points

 No non-compliance found in safety aspect and service quality performance index is between 80 and 89 points

 No non-compliance found in safety aspect and service quality performance index is between 70 and 79 points

 No non-compliance found in safety aspect and service quality performance index is less than 70 points

Note 3:

Ben Fung Machineries & Engineering Ltd. was involved in a lift incident of over-travel during maintenance happened on 26 January 2014. The incident case is under criminal proceeding.

Note 4a:

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 12/2014.

Note 4b:

Antonfield Engineering Co., Ltd. pleaded guilty to the charge for failing to notify the Director of Electrical and Mechanical Services for major alteration works on a lift. The record of non-compliance will be kept for one year until 9/2015.

Note 4c:

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 1/2015.

Note 4d:

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 6/2015.

Note 4e:

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 8/2015.

Note 4f:

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 6/2015.