

Registered Lift Contractors

Quarterly Contractors' Performance Rating (CPR) of

Registered Lift Contractors

(Assessment period: from April 2014 to March 2015) ^(Note 1)

(in alphabetical order based on the Services Quality Performance Rating)

Please select and click the respective contractor name to access the contractor's related information

Name of Contractor	Contractor No.	Safety Performance Rating <small>(Note 2)</small>	Services Quality Performance Rating <small>(Note 2)</small>
Anlev Elex Elevator Ltd.	RLC92004	★	★★★★★
Associated Engineers, Ltd.	RLC01003	★	★★★★★
Association Electrical Engineering Limited	RLC02003	★	★★★★★
Cheerwell Engineering Limited	RLC96002	★	★★★★★
Elevator Parts Engineering Company Limited	RLC78001	★	★★★★★
Hoi Fai Lift Engineering & Services Ltd.	RLC87006	★	★★★★★
Hongkong International Terminals Limited	RLC01004	★	★★★★★
Jekco Elevators Ltd.	RLC97001	★	★★★★★
Mitsubishi Elevator Hong Kong Company Limited	RLC88005	★	★★★★★
Rich Mark Engineering Limited	RLC99001	★	★★★★★
Shan On Engineering Company Limited	RLC73002	★	★★★★★
Sun Fai Engineering & Equipment Co., Ltd.	RLC02002	★	★★★★★
Taizoom Elevator Co.(H.K.)Ltd.	RLC10001	★	★★★★★
Tak Lee Elevator Engineering Co., Ltd.	RLC02001	★	★★★★★
Techfaith Engineering Limited	RLC00002	★	★★★★★
Toki Elevator Engineering Ltd.	RLC85002	★	★★★★★
Vertex Engineering Limited	RLC00001	★	★★★★★
Chun Ming Engineering Co. Ltd.	RLC88002	★	★★★★
Loedige Asia Limited	RLC07001	★	★★★★
Chevalier (HK) Limited	RLC69001	★	★★★

Chun Ming Elevator Co. Ltd.	RLC93002	★	★★★★
CKP Building Service Systems Ltd.	RLC85001	★	★★★★
Fujitec (HK) Co. Ltd. ^(Note 3)	RLC85005	★	★★★★
Hitachi Elevator Engineering Co. (HK) Ltd.	RLC67001	★	★★★★
Holake Hong Kong Lifts Ltd.	RLC80005	★	★★★★
KONE Elevator (HK) Ltd.	RLC87001	★	★★★★
Sigma Elevator (HK) Ltd.	RLC04002	★	★★★★
The Express Lift Company Limited	RLC94001	★	★★★★
Eugene Engineering Co. Limited	RLC03002	★	★★
ThyssenKrupp Elevator (HK) Limited ^(Note 4)	RLC96001	★	★★
Amanti (HK) Lift & Escalator Engineering Limited	RLC03001	★	★
Ring Hing Engineering Services Co., Ltd.	RLC97004	★	★
Lighthouse Elevator Engineering Limited	RLC98003	★	-
Antonfield Engineering Co., Ltd.	RLC95002		(Note/註 5a)
Ben Fung Machineries & Engineering Ltd	RLC73001		(Note/註 5b)
Nikkin Lifts & Escalators Limited	RLC91002		(Note/註 5c)
Otis Elevator Company (HK) Limited	RLC75004		(Note/註 5d)
Schindler Lifts (Hong Kong) Ltd	RLC74002		(Note/註 5e)

Note 1:

The list of performance rating only shows the performance rating of the contractor who had five or more lifts being inspected by the EMSD during the assessment period. In other words, for those contractors having less than five lifts being inspected by the EMSD during the assessment period [refer to Table (a)], and contractors not undertaking any lift maintenance work during the assessment period [refer to Table (b)], their performances are not included in the list of performance rating.







(a) Contractors having less than five lifts being inspected by the EMSD during the assessment period:

Name of Registered Lift Contractor	Contractor No.
Ryoden Elevator Company Limited	RLC64001

(b) Contractors not undertaking any lift maintenance work during the assessment period:

Name of Registered Lift Contractor	Contractor No.
Holake (HK) Ltd.	RLC76001
MTR Corporation Ltd.	RLC78003

Note 2:

	No non-compliance found in both safety and services quality aspects in two recent quarterly announcements (Safety Star awarded and the services quality performance index at 100 points in the two recent quarterly announcements)
	No non-compliance found in both safety and services quality aspects (performance index at 100 points in this quarterly announcement)
	No non-compliance found in safety aspect and service quality performance index is between 90 and 99 points
	No non-compliance found in safety aspect and service quality performance index is between 80 and 89 points
	No non-compliance found in safety aspect and service quality performance index is between 70 and 79 points
	No non-compliance found in safety aspect and service quality performance index is less than 70 points

Note 3:

Fujitec (HK) Co. Ltd. was involved in a lift incident of suspension rope breakage happened on 13 January 2014. A warning letter was served in 1/2014 and the record for such non-compliance was kept for 1 year till 1/2015. At present, the incident case is under criminal proceeding.

Note 4:

A lift incident happened on 8 October 2014 in an industrial building in Kwun Tong. The incident was caused by severe overload. During the investigation, the EMSD found that there were inadequacies in the maintenance works and working procedure of the lift contractor, ThyssenKrupp Elevator (HK) Limited. The EMSD will conduct a disciplinary inquiry into the case.

Note 5a:

Antonfield Engineering Co., Ltd. pleaded guilty to the charge for failing to notify the Director of Electrical and Mechanical Services for major alteration works on a lift. The record of non-compliance will be kept for one year until 9/2015.

Note 5b:

Ben Fung Machineries & Engineering Ltd. (Ben Fung) was involved in a lift incident of over-travel during maintenance happened on 26 January 2014. The Court fined Ben Fung for \$ 3,000 on 14 January 2015 regarding her failure of inputting the lift fault information and the event details in the log book. The record of non-compliance will

be kept for one year until 1/2016.

Note 5c:

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 6/2015.

Note 5d:

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 8/2015.

Note 5e:

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 6/2015.