

Contractors' Performance Rating (CPR)

Registered Lift Contractors

Quarterly Contractors' Performance Rating (CPR) of

Registered Lift Contractors

(Assessment period: from July 2014 to June 2015) ^(Note 1)

(in alphabetical order based on the Services Quality Performance Rating)

Please select and click the respective contractor name to access the contractor's related information

Name of Contractor	Contractor No.	Safety Performance Rating (Note 2)	Services Quality Performance Rating (Note 2)
Anlev Elex Elevator Ltd.	RLC92004	★	★★★★★
Associated Engineers, Ltd.	RLC01003	★	★★★★★
Association Electrical Engineering Limited	RLC02003	★	★★★★★
Chun Ming Engineering Co. Ltd.	RLC88002	★	★★★★★
Elevator Parts Engineering Company Limited	RLC78001	★	★★★★★
Hoi Fai Lift Engineering & Services Ltd.	RLC87006	★	★★★★★
Hongkong International Terminals Limited	RLC01004	★	★★★★★
Loedige Asia Limited	RLC07001	★	★★★★★
Mitsubishi Elevator Hong Kong Company Limited	RLC88005	★	★★★★★
Rich Mark Engineering Limited	RLC99001	★	★★★★★
Shan On Engineering Company Limited	RLC73002	★	★★★★★
Sun Fai Engineering & Equipment Co., Ltd.	RLC02002	★	★★★★★
Taizoom Elevator Co.(H.K.)Ltd.	RLC10001	★	★★★★★
Tak Lee Elevator Engineering Co., Ltd.	RLC02001	★	★★★★★
Techfaith Engineering Limited	RLC00002	★	★★★★★
Toki Elevator Engineering Ltd.	RLC85002	★	★★★★★
Chun Ming Elevator Co. Ltd.	RLC93002	★	★★★★
Chevalier (HK) Limited	RLC69001	★	★★★
CKP Building Service Systems Ltd.	RLC85001	★	★★★

Eugene Engineering Co. Limited ^(Note 3)	RLC03002	★	★★★★
Fujitec (HK) Co. Ltd. ^(Note 4)	RLC85005	★	★★★★
Hitachi Elevator Engineering Co. (HK) Ltd.	RLC67001	★	★★★★
Holake Hong Kong Lifts Ltd.	RLC80005	★	★★★★
KONE Elevator (HK) Ltd.	RLC87001	★	★★★★
Schindler Lifts (Hong Kong) Ltd ^(Note 5)	RLC74002	★	★★★★
The Express Lift Company Limited	RLC94001	★	★★★★
Vertex Engineering Limited	RLC00001	★	★★★★
Cheerwell Engineering Limited	RLC96002	★	★★
ThyssenKrupp Elevator (HK) Limited ^(Note 6)	RLC96001	★	★★
Jekco Elevators Ltd.	RLC97001	★	★
Sigma Elevator (HK) Ltd.	RLC04002	★	★
Lighthouse Elevator Engineering Limited	RLC98003	★	-
Nikkin Lifts & Escalators Limited	RLC91002	★	-
Ring Hing Engineering Services Co., Ltd.	RLC97004	★	-
Antonfield Engineering Co., Ltd.	RLC95002		(Note/註 7a)
Ben Fung Machineries & Engineering Ltd	RLC73001		(Note/註 7b)
Otis Elevator Company (HK) Limited	RLC75004		(Note/註 7c)

Note 1:

The list of performance rating only shows the performance rating of the contractor who had five or more lifts being inspected by the EMSD during the assessment period. In other words, for those contractors having less than five lifts being inspected by the EMSD during the assessment period [refer to Table (a)], and contractors not undertaking any lift maintenance work during the assessment period [refer to Table (b)], their performances are not included in the list of performance rating.

(a) Contractors having less than five lifts being inspected by the EMSD during the assessment period:

Name of Registered Lift Contractor

Contractor No.

—

—

(b) Contractors not undertaking any lift maintenance work during the assessment period:

Name of Registered Lift Contractor	Contractor No.
Holake (HK) Ltd.	RLC76001
MTR Corporation Ltd.	RLC78003
Ryoden Elevator Company Limited	RLC64001

Note 2:



No non-compliance found in both safety and services quality aspects in two recent quarterly announcements (Safety Star awarded and the services quality performance index at 100 points in the two recent quarterly announcements)



No non-compliance found in both safety and services quality aspects (performance index at 100 points in this quarterly announcement)



No non-compliance found in safety aspect and service quality performance index is between 90 and 99 points



No non-compliance found in safety aspect and service quality performance index is between 80 and 89 points



No non-compliance found in safety aspect and service quality performance index is between 70 and 79 points



No non-compliance found in safety aspect and service quality performance index is less than 70 points

Note 3:

Eugene Engineering Co. Limited (Eugene) was involved in an industrial incident during rope replacement happened on 5 August 2014. The Court fined Eugene for \$6,000 on 3 July 2015 regarding her failure to ensure that adequate safety precautions were taken. The record of non-compliance will be announced in the next quarter.

Note 4:

Fujitec (HK) Co. Ltd. was involved in a lift incident of suspension rope breakage happened on 13 January 2014. A warning letter was served in 1/2014 and the record for such non-compliance was kept for 1 year till 1/2015. At present, the incident case is under criminal proceeding.

Note 5:

Schindler Lifts (Hong Kong) Ltd. was involved in a lift incident of suspension rope breakage happened on 8 May 2014. A warning letter was served in 6/2014 and the record for such non-compliance was kept for 1 year till 6/2015. At present, the incident case is under criminal proceeding.

Note 6:

A lift incident happened on 8 October 2014 in an industrial building in Kwun Tong. The incident was caused by severe overload. During the investigation, the EMSD found that there were inadequacies in the maintenance works

and working procedure of the lift contractor, ThyssenKrupp Elevator (HK) Limited. The EMSD will conduct a disciplinary inquiry into the case.

Note 7a:

Antonfield Engineering Co., Ltd. (Antonfield) pleaded guilty to the charge for failing to notify the Director of Electrical and Mechanical Services for major alteration works on a lift. The Court fined Antonfield for \$ 5,000 on 4 March 2015 for the contravention of the Lift and Escalator (General) Regulation (Cap.618A). Criminal proceeding of the case was completed in September 2014. The record of non-compliance will be kept for one year until 9/2015.

Note 7b:

Ben Fung Machineries & Engineering Ltd. (Ben Fung) was involved in a lift incident of over-travel during maintenance happened on 26 January 2014. The Court fined Ben Fung for \$ 3,000 on 14 January 2015 regarding her failure of inputting the lift fault information and the event details in the log book. The record of non-compliance will be kept for one year until 1/2016.

Note 7c:

Non-compliance found in safety aspect, thus served with warning letter. The record of non-compliance will be kept for one year until 8/2015.