

**Lift Equipment Failure Incident reported to EMSD (Jan 2020 to Dec 2020)**

<b>Contractor No.</b>	<b>Name of Contractor</b>	<b>Incident Date</b>	<b>Location</b>	<b>Incident Nature</b>
RLC75004	Otis Elevator Company (H.K.) Ltd.	15/01/2020	TWCHS Jockey Club Rehabilitation Complex, 4 Welfare Road, Wong Chuk Hang, Hong Kong	Malfunction of electrical component resulting in passenger injury
RLC87001	Kone Elevator (HK) Ltd.	11/03/2020	Lok Nga Court, Ngau Tau Kok, Kowloon	Malfunction of electrical component resulting in passenger injury
RLC94001	The Express Lift Co. Ltd.	08/06/2020	Merit Industrial Centre, 94 To Kwa Wan Road, To Kwa Wan, Kowloon	Malfunction of electrical component resulting in passenger injury
RLC75004	Otis Elevator Company (H.K.) Ltd.	03/07/2020	The Legend, 23 Tai Hang Drive, Tai Hang, Hong Kong	Malfunction of mechanical component resulting in passenger injury
RLC04002	Sigma Elevator (HK) Ltd.	05/07/2020	Block 4, Broadview Court, 11 Shum Wan Road, Wong Chuk Hang, Hong Kong	Malfunction of electrical component resulting in passenger injury
RLC69001	Chevalier (HK) Limited	23/07/2020	Sunbeam Centre, 27 Shing Yip Street, Kwun Tong, Kowloon	Malfunction of electrical component resulting in passenger injury
RLC74002	Schindler Lifts (Hong Kong) Ltd.	20/08/2020	Kowloon Bay International Trade & Exhibition Centre, 1 Trademart Drive, Kowloon Bay, Kowloon	Malfunction of electrical component resulting in passenger injury
RLC69001	Chevalier (HK) Limited	26/08/2020	Block C1, Kornhill, Quarry Bay, Hong Kong.	Malfunction of electrical component resulting in unintended car movement and passenger injury
RLC74002	Schindler Lifts (Hong Kong) Ltd.	12/10/2020	Chuk Yuen North Estate, Wong Tai Sin, Kowloon	Malfunction of electrical component resulting in passenger injury
RLC75004	Otis Elevator Company (H.K.) Ltd.	14/10/2020	Leung Wai House, Leung King Estate, Tuen Mun, N.T.	Malfunction of electrical component resulting in passenger injury
RLC69001	Chevalier (HK) Limited	26/10/2020	Cavendish Heights, 33 Perkins Road, Tai Hang, Hong Kong	Malfunction of mechanical component resulting in passenger injury
RLC87001	Kone Elevator (HK) Ltd.	18/12/2020	Princess Margarat Hospital Block E&F, 2-10 Hospital Road, Kwai Chung, N.T.	Passenger struck by a lamp diffuser dropped from the recessed lamp installed at the ceiling of lift car.

No. of Equipment Failure Records = 12