

Lift Equipment Failure Incident reported to EMSD (Jan 2022 to Dec 2022)

Contractor No.	Name of Contractor	Incident Date	Location	Incident Nature
RLC87001	Kone Elevator (HK) Ltd.	20/01/2022	Kwai Hing Station of MTRC, Kwai Hing, N.T.	Passenger tripping due to levelling difference of lift car at landing arisen from levelling device malfunction.
RLC74002	Schindler Lifts (Hong Kong) Ltd.	12/03/2022	Block 7, Hong Kong Gold Coast, Tuen Mun, N.T.	Passenger tripping due to levelling difference of lift car at landing arisen from levelling device malfunction.
RLC74002	Schindler Lifts (Hong Kong) Ltd.	16/03/2022	Block 4, Fung Tak Estate, Diamond Hill, Wong Tai Sin, Kowloon	Passenger tripping due to levelling difference of lift car at landing arisen from levelling device malfunction.
RLC85005	Fujitec (HK) Co., Ltd.	27/03/2022	Block 2, Fung Tak Estate, Diamond Hill, Wong Tai Sin, Kowloon	Passenger tripping due to levelling difference of lift car at landing arisen from levelling device malfunction.
RLC69001	Chevalier (HK) Limited	02/04/2022	Yeung King House, Lai King Estate, Lai King, Kowloon	Passenger tripping due to levelling difference of lift car at landing arisen from levelling device malfunction.
RLC75004	Otis Elevator Company (H.K.) Ltd.	12/04/2022	Cheung King House, Siu Shan Court, Tuen Mun, N.T.	Passenger tripping due to levelling difference of lift car at landing arisen from levelling device malfunction.
RLC02003	Association Electrical Engineering Limited	15/05/2022	On Yun House, Cheung On Estate, Tsing Yi, N.T.	Emergency stop of travel due to malfunction of PCB causing the trigger of control drive fault resulting in passenger entrapment.
RLC74002	Schindler Lifts (Hong Kong) Ltd.	18/05/2022	Chuk Yuen North Estate, Wong Tai Sin, Kowloon	Passenger tripping due to levelling difference of lift car at landing arisen from levelling device malfunction.
RLC74002	Schindler Lifts (Hong Kong) Ltd.	24/05/2022	HK Convention & Exhibition Centre Office Tower, 1 Harbour Road, Wan Chai, Hong Kong	Emergency stop of travel due to failure of contactor controlling the operation of the lift motor resulting in passenger entrapment.
RLC69001	Chevalier (HK) Limited	30/05/2022	Tsui Yiu Court, 1 Lai Chi Ling Road, Kwai Chung, N.T.	Passenger tripping due to levelling difference of lift car at landing arisen from levelling device malfunction.
RLC85005	Fujitec (HK) Co., Ltd.	02/06/2022	King Min House, King Lam Estate, 38 Po Lam Road North, Tseung Kwan O, N.T.	Passenger tripping due to levelling difference of lift car at landing arisen from levelling device malfunction.
RLC75004	Otis Elevator Company (H.K.) Ltd.	12/06/2022	O.T.B. Building, 160 Gloucester Road, Wan Chai, Hong Kong	Occurrence of unintended car movement due to failure of brake system.
RLC69001	Chevalier (HK) Limited	01/08/2022	Well On Garden, 9 Yuk Nga Lane, Tseung Kwan O, N.T.	Abnormal door closing due to malfunction of electrical component resulting in passenger injury.
RLC85005	Fujitec (HK) Co., Ltd.	24/08/2022	Hong Fai Building, 64-68 Wing Hong Street, Sham Shui Po, Kowloon	Passenger tripping due to levelling difference of lift car at landing arisen from levelling device malfunction.
RLC74002	Schindler Lifts (Hong Kong) Ltd.	03/10/2022	Ocean Supreme, 100 Tai Ho Road, Tsuen Wan, N.T.	Passenger tripping due to levelling difference of lift car at landing arisen from levelling device malfunction.
RLC75004	Otis Elevator Company (H.K.) Ltd.	04/11/2022	Tin Mei House, Tin Ping Estate, 48 Tin Ping Road, Sheung Shui, N.T.	Passenger tripping due to levelling difference of lift car at landing arisen from levelling device malfunction.
RLC02003	Association Electrical Engineering Limited	07/11/2022	Man Sun House, 163-173 Portland Street, Mong Kok, Kowloon	Passenger tripping due to levelling difference of lift car at landing arisen from levelling device malfunction.
RLC85005	Fujitec (HK) Co., Ltd.	01/12/2022	Golden Industrial Building, 16-26 Kwai Tak Street, Kwai Chung, N.T.	Breakage of suspension ropes due to lift car stuck in the liftway while the drive sheave was still revolving.

No. of Equipment Failure Records = 18