

### Lift Equipment Failure Incident reported to EMSD (from January 2016 to December 2016)

Contractor No.	Name of Contractor	Incident Date	Location	Incident Nature
RLC91002	Nikkin Lifts & Escalators Limited	28/12/2015 <sup>Note 1</sup>	World Wide Industrial Centre, 43-47 Shan Mei Street, Fo Tan, N.T.	Passenger injury due to malfunction of electrical component
RLC69001	Chevalier (HK) Limited	22/01/2016	King On House, Shan King Estate, Tuen Mun, N.T.	Passenger injury due to malfunction of mechanical component
RLC80005	Holake Hong Kong Lifts Ltd.	24/04/2016	Tai Hing Mansion, 119-127 Des Voeux Road West, Sai Ying Pun, Hong Kong	Main drive failure due to broken of the shaft for supporting traction sheave of the traction machine
RLC69001	Chevalier (HK) Limited	04/06/2016	New Town Plaza, 18 Sha Tin Centre Street, Sha Tin, N.T.	Passenger injury due to malfunction of electrical component
RLC04002	Sigma Elevator (HK) Ltd.	18/06/2016	Mui Wo Government Offices, 2 Ngan Kwong Wan Road, Lantau, N.T.	Passenger injury due to malfunction of electrical component
RLC74002	Schindler Lifts (Hong Kong) Ltd.	26/06/2016	May Shing Court, Tai Wai, Shatin, N.T.	Passenger injury due to malfunction of mechanical component
RLC69001	Chevalier (HK) Limited	12/07/2016	Block K, Amoy Plaza Phase II, Kowloon Bay	Passenger injury due to malfunction of electrical component
RLC03002	Eugene Engineering Co. Limited	07/08/2016	Tai Po Building, 38 Kwong Fuk Road, Tai Po, N.T.	Passenger injury due to malfunction of electrical component
RLC99001	Rich Mark Engineering Ltd.	17/11/2016	Kin Ho Industrial Building, 14-24 Au Pui Wan Street, Fo Tan, N.T.	Main drive failure due to fracture of fixing bolts inside the gear box of traction machine
RLC10001	Taizoom Elevator Co. (HK) Ltd.	02/12/2016	Han Hing Building Block (A, B), 1-3 Fuk Wa Street, Sham Shui Po, Kowloon	Main drive failure due to excessive wear of gear of traction machine
RLC75004	Otis Elevator Company (HK) Limited	19/12/2016	Footbridge at Ching Wah Court, Tsing Yi, N.T.	Main drive failure due to broken shaft between motor and gearbox of traction machine

No. of Equipment Failure Records = 11

Note 1 : Incident is recorded in 2016