

## Escalator Equipment Failure Incident reported to EMSD (Jan 2021 to Dec 2021)

Contractor No.	Name of Contractor	Incident Date	Location	Incident Nature
REC80001	Holake Hong Kong Lifts Ltd.	26/01/2021	Citiplaza Stage VA, Taikoo Shing Road, Tai Koo Shing, Hong Kong	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC75003	Otis Elevator Company (HK) Ltd.	31/01/2021	Metroplaza, 223 Hing Fong Road, Kwai Chung, N.T.	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC74002	Schindler Lifts (HK) Ltd.	22/02/2021	Chi Fu Landmark, Chi Fu Fa Yuen, Pok Fu Lam Road, Pok Fu Lam, Hong Kong	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC85004	Fujitec (HK) Co., Ltd.	22/02/2021	MOSTown, 18 On Luk Street, Ma On Shan, N.T.	Protruded steel wire from the surface of the handrail of an escalator resulting in passenger injury.
REC75003	Otis Elevator Company (HK) Ltd.	22/03/2021	MTR Corporation, Kam Sheung Road Station, Yuen Long, N.T.	Burning smell from brake mechanism due to malfunction of electrical component and caused brake engaged while the escalator continues running.
REC96001	TK Elevator (HK) Limited	15/04/2021	Worfu, 21-53 Wharf Road, North Point, Hong Kong	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC88002	Mitsubishi Elevator Hong Kong Company Limited	09/05/2021	Kwai Chung Plaza, 7-11 Kwai Foo Road, Kwai Chung, N.T.	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC87001	KONE Elevator (HK) Ltd.	30/05/2021	Circulation Core, Yau Tong Estate, Yau Tong, Kowloon	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC85004	Fujitec (HK) Co., Ltd.	30/06/2021	Lee Theatre Plaza, 99 Percival Street, Causeway Bay, Hong Kong	Emergency stop of the escalator due to breakage of a step supporting roller and triggered the step sagging safety switch resulting in passenger injury.
REC69001	Chevalier (HK) Limited	26/07/2021	New Town Plaza Phase 1, 18 Sha Tin Centre Street, Sha Tin, N.T.	Sudden stop of the left handrail due to breakage of a handrail drive chain resulting in passenger injury.
REC75003	Otis Elevator Company (HK) Ltd.	18/08/2021	Optimall, 118 Chuen Lung Street, Tsuen Wan, N.T.	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC80001	Holake Hong Kong Lifts Ltd.	12/09/2021	39-41 Junk Bay Area, Tseung Kwan O, N.T.	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC74002	Schindler Lifts (HK) Ltd.	08/10/2021	Mega Box, Enterprise Square 5, 38 Wang Chiu Road, Kowloon Bay, Kowloon	Protruded steel wire from the surface of the handrail of an escalator resulting in passenger injury.
REC88002	Mitsubishi Elevator Hong Kong Company Limited	10/10/2021	Whampoa Garden, Site 11, Hung Hom, Kowloon	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC74002	Schindler Lifts (HK) Ltd.	13/10/2021	Choi Ming Shopping Centre Extension, Kin Ming Estate, Tseung Kwan O, N.T.	Emergency stop of the escalator due to breakage of a bushing between the step & drive chain and triggered the combplate safety switch resulting in passenger injury.

REC74002	Schindler Lifts (HK) Ltd.	23/10/2021	Yat Chau International Plaza, 118 Connaught Road West, Central, Hong Kong	Emergency stop of the escalator due to breakage of a step supporting roller and triggered the step sagging safety switch resulting in passenger injury.
----------	---------------------------	------------	---	---

No. of Equipment Failure Records = 16