

Escalator Equipment Failure Incident reported to EMSD (Jan 2023 to Dec 2023)

Contractor No.	Name of Contractor	Incident Date	Location	Incident Nature
REC74002	Schindler Lifts (HK) Ltd.	09/01/2023	Footbridge at Pui Shing Road, Hang Hau, Tseung Kwan O, N.T.	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC85004	Fujitec (HK) Co., Ltd.	09/01/2023	Pop Corn, 9 Tong Yin Street, Tseung Kwan O, N.T.	Emergency stop of the escalator due to malfunction of missing step device resulting in passenger injury.
REC85004	Fujitec (HK) Co., Ltd.	23/02/2023	Regal Kowloon Hotel, 71 Mody Road, Tsim Sha Tsui, Kowloon	Protruded steel wire from the surface of the handrail of an escalator resulting in passenger injury.
REC69001	Chevalier (HK) Limited	23/02/2023	Tropicana Gardens, 110 Kung Cheung Road, Wong Tai Sin, Kowloon	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC74002	Schindler Lifts (HK) Ltd.	04/04/2023	Chi Fu Landmark, Pokfulam, Hong Kong	Protruded steel wire from the surface of the handrail of an escalator resulting in passenger injury.
REC75003	Otis Elevator Company (HK) Ltd.	12/05/2023	Plaza Hollywood, 3 Lung Poon Street, Wong Tai Sin, Kowloon	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC75003	Otis Elevator Company (HK) Ltd.	07/06/2023	Kowloon Tong Station, Kowloon Tong, Kowloon	Emergency stop of the escalator due to poor contact of wirings at the inspection socket resulting in passenger injury.
REC69001	Chevalier (HK) Limited	19/07/2023	Tsuen Wan Plaza, 4-30 Tai Pa Street, Tsuen Wan, N.T.	Protruded steel wire from the surface of the handrail of an escalator resulting in passenger injury.
REC75003	Otis Elevator Company (HK) Ltd.	30/08/2023	Plaza Hollywood, 3 Lung Poon Street, Wong Tai Sin, Kowloon	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC87001	Kone Elevator (HK) Ltd.	06/09/2023	Footbridge No. NF109 Across Castle Peak Road Near Fou Wah Centre, Tsuen Wan, N.T.	Protruded steel wire from the surface of the handrail of an escalator resulting in passenger injury.
REC75003	Otis Elevator Company (HK) Ltd.	02/10/2023	Shopping Arcade, Kai Tak Garden Phase 2, 121 Choi Hung Road, Wong Tai Sin, Kowloon	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC75003	Otis Elevator Company (HK) Ltd.	15/10/2023	Yau Ma Tei Station, Yau Ma Tei, Kowloon	Emergency stop of the escalator due to poor contact of wirings at the control circuit resulting in passenger injury.
REC75003	Otis Elevator Company (HK) Ltd.	18/11/2023	Fuller Garden, 8 Chui Lok Street, Tai Po, N.T.	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.

No. of Equipment Failure Records = 13