

Escalator Equipment Failure Incident reported to EMSD (Jan 2024 to Dec 2024)

Contractor No.	Name of Contractor	Incident Date	Location	Incident Nature
REC75003	Otis Elevator Company (HK) Ltd.	04/05/2024	Tuen Mun Station, Tuen Mun, N.T.	Smoldering on the brake lining due to poor adjustment of brake mechanism.
REC74002	Schindler Lifts (HK) Ltd.	07/05/2024	Chi Fu Landmark, Chi Fu Fa Yuen, Pok Fu Lam Road, Pok Fu Lam, Hong Kong	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC75003	Otis Elevator Company (HK) Ltd.	15/06/2024	26 Nathan Road, Tsim Sha Tsui, Kowloon	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC74002	Schindler Lifts (HK) Ltd.	14/11/2024	Tuen Mun Town Plaza, Tuen Mun, N.T..	Emergency stop of the escalator due to insufficient tension of motor drive chain resulting in passenger injury.
REC88002	Mitsubishi Elevator Hong Kong Company Limited.	06/12/2024	Richland Garden, 138 Wu Chui Road, Tuen Mun, N.T.	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.
REC88002	Mitsubishi Elevator Hong Kong Company Limited.	06/12/2024	Richland Garden, 138 Wu Chui Road, Tuen Mun, N.T.	Unsynchronized handrail operation of an escalator due to malfunction of handrail drive unit resulting in passenger injury.

No. of Equipment Failure Records = 6