

五款有過熱安全風險的拖板

5 Models of Extension Units with Overheating Safety Risks

	<p>品牌 Brand</p>	<p>型號 Model</p>	<p>圖片 Photo</p>
<p>1</p>	<p>REMAX</p>	<p>RU-S4</p>	 <p>The image shows a black REMAX RU-S4 extension unit with a power cord and a multi-pin connector. Below it is the product packaging, which is black and red, featuring the text 'ALIENS REMAX RU-S4 5USB' and '6 OUTLETS ANTI-SHAKE POWER STRIP'.</p>
<p>2</p>	<p>LDNIO</p>	<p>SC3301</p>	 <p>The image shows a white LDNIO SC3301 extension unit with a power cord and a USB connector. Below it is the product packaging, which is gold and black, featuring the text 'LDNIO SC3301 3058' and '3 IN 1'.</p>
<p>3</p>	<p>LDNIO</p>	<p>SC3604</p>	 <p>The image shows a white LDNIO SC3604 extension unit with a power cord and a multi-pin connector. Below it is the product packaging, which is white and black, featuring the text 'LDNIO SC3604 6 USB' and '6 POWER POINT ANTI-SHAKE OVER-SOCKET'.</p>

4	沒有品牌名稱 No Brand Name	ZGN-T06	
5	沒有品牌名稱 No Brand Name	ZGN-T08	