## Contractors' Performance Rating (CPR) (From June 2010 to May 2011) (Note 1)

Name of Contractors (in alphabetical order)	Contractor No.	No. of prosecution cases in the assessment period	No. of disciplinary cases in the assessment period	Previous Performance Index (March 2010 to February 2011)	June 2010 to May 2011				
					Cumulated Maintenance PM Points	No. of Lifts Inspected	Maintenance Index (Note 2)	Safety Index (Note 2)	Performance Index
ANLEV Elex Elevator Ltd.	RLC92004			89	14	61	39	50	89
Antonfield Engg. Co. Ltd.	RLC95002			74	9	15	20	50	70
Association Electrical Engineering Limited	RLC02003			94	4	36	44	50	94
Ben Fung Machineries & Engg. Ltd.	RLC73001			85	0	39	50	50	100
Cheerwell Engineering Limited	RLC96002			55	0	12	50	50	100
Chevalier (HK) Ltd.	RLC69001	<b> </b>	-	96	23	382	47	50	97
Chun Ming Elevator Company Ltd.	RLC93002	1		85	6	45	43	35	78
Chun Ming Engineering Co. Ltd.	RLC93002	'	1	99	0	83	50	50	100
CKP Building Service Systems Ltd.	RLC85001		-	80	2	12	42	50	92
, ,	RLC78001			70	18	30	20	50	70
Elevator Parts Engg. Co. Ltd.	RLC/3001			58	22	22	0	50	50
Eugene Engineering Co. Limited							40		
Fujitec (HK) Co. Ltd.	RLC85005			89	81	397		50	90
Hitachi Elevator Engg. Co. (HK) Ltd.	RLC67001			96	20	181	44	50	94
Hoi Fai Lift Engg. & Services Ltd.	RLC87006			100	0	11	50	50	100
Holake Hong Kong Lifts Ltd.	RLC80005			83	58	206	36	50	86
Hongkong International Terminals Limited	RLC01004			100	0	12	50	50	100
Jekco Elevators Ltd.	RLC97001			81	10	22	27	50	77
KONE Elevator (H.K.) Ltd.	RLC87001			92	63	301	40	50	90
Lighthouse Elevator Engineering Limited	RLC98003			57	58	66	6	50	56
Mitsubishi Elevator Hong Kong Company Limited	RLC88005			81	28	414	47	35	82
Nikkin Lift & Escalator Services Ltd.	RLC91002			66	74	185	30	50	80
Otis Elevator Co. (HK) Ltd.	RLC75004	2		73	184	539	33	35	68
Rich Mark Engineering Limited	RLC99001			91	0	32	50	50	100
Ring Hing Engineering Services Co., Ltd.	RLC97004			94	6	52	44	50	94
Ryoden Lift Services Ltd.	RLC99002			86	6	23	37	50	87
Schindler Lifts (HK) Ltd.	RLC74002			91	83	539	42	50	92
Shan On Engineering Co. Ltd.	RLC73002			98	3	59	47	50	97
Shineford Engineering Ltd.	RLC97002			72	0	14	50	50	100
Sigma Elevator (HK) Limited	RLC04002			78	72	120	20	50	70
Southa Technical Limited	RLC01002			90	4	16	38	50	88
Sun Fai Engineering & Equipment Co., Ltd.	RLC02002			67	12	17	15	50	65
Tak Lee Elevator Engineering Co., Ltd.	RLC02001			100	0	8	50	50	100
Techfaith Engineering Limited	RLC00002			57	0	7	50	50	100
The Express Lift Company Limited	RLC94001			96	24	134	41	50	91
ThyssenKrupp Elevator (HK) Limited	RLC96001		1	91	6	113	47	50	97
Toki Elevator Engineering Ltd.	RLC85002			88	12	38	34	50	84
Vertex Engineering Limited	RLC00001			100	0	11	50	50	100

Note 1 ·

For a better reflection of the contractors' performance in the assessment period, only the CPR results of Contractors whose installations inspected by EMSD for 5 times or more will be included in the table. It does not include (a) the contractors whose installations inspected by EMSD are less than 5 times and (b) contractors who do not undertake any lift maintenance work during the assessment period.

(a) Contractors whose installations inspected by EMSD were less than 5 times during the assessment period

Contractor No.		
RLC03001		
RLC01003		
RLC07001		
RLC10001		

(b) Contractors who did not undertake any lift maintenance work during the assessment period

Name of Registered Lift Contractor	Contractor No.
CNIM Hong Kong Ltd.	RLC88004
Group Creation International Limited	RLC04001
Hang Fung Lift Ltd.	RLC88003
Holake (HK) Ltd.	RLC76001
MTR Corporation Ltd.	RLC78003
Ryoden Elevator Company Limited	RLC64001
Whole Safe Ltd.	RLC92001

Note 2 .

Performance Index (Full mark of 100) = Maintenance Index (0 to 50 marks) + Safety Index (0 to 50 marks); Maintenance Index = 50 x (1- cumulated maintenance performance monitoring points (each critical safety non-compliant item with 15 Points). The cumulated performance monitoring points are valid for 12 months. Details of the maintenance and safety items can be observed from http://www.emsd.gov.hk/emsd/e\_download/pps/circular/A3/2\_2011.pdf.