

Lift Equipment Failure Incident reported to EMSD (January 2017 to December 2017)

Contractor No.	Name of Contractor	Incident Date	Location	Incident Nature
RLC75004	Otis Elevator Company (HK) Limited	23/02/2017	Central Plaza, 18 Harbour Road, Wan Chai, Hong Kong	Malfunction of electrical component resulting in passenger injury
RLC69001	Chevalier (HK) Limited	21/03/2017	Wing Fat Commercial Building, 216-218 Aberdeen Main Road, Aberdeen, Hong Kong	Failure of brake system resulting in passenger trapping
RLC69001	Chevalier (HK) Limited	13/05/2017	Kwai Sing Centre, 1-8 Wo Yi Hop Road, Kwai Chung, N.T.	Failure of braking system resulting in passenger injury
RLC67001	Hitachi Elevator Engineering Co. (HK) Ltd.	20/05/2017	Bellagio, 33 Castle Peak Road, Sham Tseng, N.T.	Malfunction of lift car levelling system resulting in passenger injury
RLC94001	The Express Lift Company Limited	25/05/2017	1 Hung To Road, Kwun Tong, Kowloon	Malfunction of mechanical component resulting in passenger injury
RLC75004	Otis Elevator Company (HK) Limited.	30/05/2017	Leung Wai House, Leung King Estate, Tuen Mun, N.T.	Malfunction of lift car levelling system resulting in passenger injury
RLC94001	The Express Lift Company Limited	04/06/2017	Tai Kung Building, 117 Tai Kok Tsui Road, Tai Kok Tsui, Kowloon	Malfunction of lift car levelling system resulting in passenger injury
RLC85005	Fujitec (HK) Co. Ltd.	15/11/2017	King Min House, King Lam Estate, Tseung Kwan O, N.T.	Malfunction of interlock and safety devices resulting in an industrial accident

No. of Equipment Failure Records = 8