

**Lift Equipment Failure Incident reported to EMSD (Jan 2019 to Dec 2019)**

<b>Contractor No.</b>	<b>Name of Contractor</b>	<b>Incident Date</b>	<b>Location</b>	<b>Incident Nature</b>
RLC96002	Cheerwell Engineering Ltd.	30/03/2019	Academic Terrace, 101 Pok Fu Lam Road, Kennedy Town, Hong Kong	Malfunction of mechanical component resulting in passenger injury
RLC74002	Schindler Lifts (Hong Kong) Ltd.	06/06/2019	Block 2, Les Saisons, 28 Tai On Street, Shau Kei Wan, Hong Kong	Breakage of one of the suspension ropes
RLC74002	Schindler Lifts (Hong Kong) Ltd.	18/06/2019	West Tower, Shun Tak Centre, 168-220 Connaught Road Central, Central, Hong Kong	Malfunction of mechanical component resulting in passenger injury
RLC04002	Sigma Elevator (HK) Limited	22/06/2019	The Court of Final Appeal, 8 Jackson Road, Central, Hong Kong	Malfunction of mechanical component resulting in passenger injury
RLC74002	Schindler Lifts (Hong Kong) Ltd.	30/07/2019	Exchange Square, Connaught Road Central, Central, Hong Kong	Malfunction of electrical component resulting in passenger injury
RLC74002	Schindler Lifts (Hong Kong) Ltd.	16/12/2019	Chater House, 8 Connaught Road Central, Central, Hong Kong	Malfunction of electrical component resulting in passenger injury

No. of Equipment Failure Records = 6