

Lift Equipment Failure Incident reported to EMSD (from January to December 2012)

Contractor No.	Name of Contractor	Incident Date	Location	Incident Nature
RLC69001	Chevalier (HK) Limited	10/02/12	San Toi Building, 137-139 Connaught Road, Central	Passenger entrapment due to defective electrical component
RLC74002	Schindler Lifts (Hong Kong) Ltd	05/07/12	Chuk Yuen Estate North, Wong Tai Sin	Passenger entrapment due to defective electrical component
		16/09/12	Butterfly On Victoria, 31-33 King's Road, North Point	Passenger entrapment due to defective mechanical component
		25/11/12	Luk Yeung Sun Chuen, Tsuen Wan	Passenger entrapment due to defective electrical component
RLC75004	Otis Elevator Company (HK) Limited	01/02/12	Kamga Mansion, 4-16 Pine Street, Tai Kok Tsui	Passenger's loss balance due to fault signal of the levelling device
		05/04/12	The Sea Crest, 1 Hang Kwai Street, Tuen Mun	Passenger entrapment due to breakage of suspension rope
		30/04/12	Li Po Chun Chambers, 185-195 Des Voeux Road Central, Central	Smoke due to defective electrical component
		27/10/12	Villa By the Peak, 139 Castle Peak Road, Yuen Long	Passenger entrapment due to defective electrical component
RLC80005	Holake Hong Kong Lifts Ltd.	18/05/12	Chinachem Tower, 34-37 Connaught Road Central, Central	Passenger entrapment due to defective electrical component
RLC91002	Nikkin Lifts & Escalators Limited	09/02/12	Eastern Factory Building, 42-50 Kwai Ting Road, Kwai Chung	Passenger's loss balance due to fault signal of control device
		20/04/12	Greenfield Garden, 2-20 Palm Street, Tai Kok Tsui	Passenger entrapment due to defective electrical component
RLC92004	Anlev Elex Elevator Ltd.	21/08/12	Providence Garden for Rehab, 82 Tsun Wen Road, Tuen Mun	Passenger entrapment due to defective electrical component
RLC94001	The Express Lift Company Limited	18/02/12	Tuen Mun Town Plaza, Tuen Mun	Passenger entrapment due to defective electrical component
		02/03/12	Wing Wah Mansion, 122-128 Electric Road, North Point	Passenger entrapment due to defective electrical component
RLC96001	ThyssenKrupp Elevator (HK) Limited	19/05/12	Riviera Mansion, 59-65 Paterson Street, Causeway Bay	Fire due to defective electrical component
RLC97001	Jekco Elevators Ltd.	09/11/12	Fook Yip Building, Kwai Chung	Passenger's entrapment due to defective electrical component
RLC97002	Shineford Engineering Limited	30/06/12	Fu Hop Factory Building, 209-211 Wai Yip Street, Kwun Tong	Passenger's loss balance due to mechanical component
		13/09/12	Kwun Tong Industrial Centre, 436-484 Kwun Tong Road, Kwun Tong	Fire due to defective electrical component
RLC98003	Lighthouse Elevator Engineering Limited	22/12/12	Lung Teck Mansion, 21-39 Ngan Hon Street, To Kwa Wan	Passenger entrapment due to defective mechanical component
RLC99001	Rich Mark Engineering Limited	06/04/12	Yue Man Centre, 300-302 Ngau Tau Kok Road, Kwun Tong	Passenger entrapment due to breakage of suspension rope

No. of Equipment Failure Records = 20