Contractors' Performance Rating (CPR) (From March 2010 to February 2011) (Note 1)

01003 87006 01004 02001 000001 88002 773002 67001 69001 994001 022003	No. of prosecution cases in the assessment period	No. of disciplinary cases in the assessment period	Performance Index from December 2009 to November 2010 (with new calculation method) Note 3 89 100 100	Cumulated Maintenance PM Points 0 0	No. of Lifts Inspected	Maintenance Index (Note 2)	Safety Index (Note 2)	Performance Index
01003 87006 101004 022001 00001 88002 73002 67001 69001 94001	prosecution cases in the assessment	disciplinary cases in the assessment period	Index from December 2009 to November 2010 (with new calculation method) Note 3 89 100	Maintenance PM Points 0 0	5	(Note 2) 50	(Note 2)	
01003 87006 101004 022001 00001 88002 73002 67001 69001 94001	prosecution cases in the assessment	disciplinary cases in the assessment period	December 2009 to November 2010 (with new calculation method) Note 3 89	Maintenance PM Points 0 0	5	(Note 2) 50	(Note 2)	
87006 001004 002001 000001 88002 73002 67001 69001			89 100	0				100
01004 02001 00001 88002 73002 67001 94001			100		13	=0		100
02001 000001 88002 73002 67001 69001						50	50	100
73002 67001 69001 94001			100	0	9	50	50	100
88002 73002 67001 69001			100	0	9	50	50	100
73002 67001 69001			100	0	11	50	50	100
67001 69001 94001		1	93	2	74	49	50	99
69001 94001	l		98	3	77	48	50	98
69001 94001	1		97	16	227	46	50	96
94001			96	29	405	46	50	96
			94	10	121	46	50	96
			96	4	36	44	50	94
97004			86	6	54	44	50	94
87001			94	57	342	42	50	92
74002			92	94	542	41	50	91
96001		1	85	21	118	41	50	91
99001			92	6	33	41	50	91
01002			85	6	31	40	50	90
85005			91	91	418	39	50	89
92004			80	14	63	39	50	89
85002			92	8	34	38	50	88
99002			91	6	22	36	50	86
73001			85	0	16	50	35	85
93002			77	0	44	50	35	85
								83
								81
						· ·		81
								80
	2							79
	_							78
			75	9	17	24	50	74
	2				544			73
	_		71	10	18	22	50	72
			83	18	30	20	50	70
			57	12	18	17	50	67
			71	106	285	31	35	66
			73	22	26	8	50	58
			79	42	49	7	50	57
			80	6	7	7	50	57
			87	9	10	5	50	55
	293002 280005 280005 280005 280005 280005 280005 280001 203001 204002 295002 275004 297002 2778001 202002 291002 203002 298003 200002 296002	C80005 288005 288005 287001 285001 203001 2 204002 295002 275004 2 297002 2758001 202002 291002 291002 298003 200002	C80005 S88005 C88005 C88006 C87001 C86001 C93001 C93001 C930002 C75004 C93002 C75004 C93002 C93003 C93002 C93003	C80005 91 288005 82 287001 68 285001 77 203001 2 79 204002 79 295002 75 275004 2 78 297002 71 278001 83 202002 57 291002 71 203002 73 298003 79 200002 80	C80005 91 56 C80005 82 28 C80005 82 28 C80001 68 10 C85001 77 8 C30001 2 79 6 C04002 79 68 3 C75004 2 78 134 C97002 71 10 3 C758001 83 18 C02002 57 12 C910002 71 106 C030002 73 22 C98003 79 42 C00002 80 6	280005 91 56 164 280005 82 28 373 287001 68 10 26 285001 77 8 20 203001 2 79 6 14 204002 79 68 154 285002 75 9 17 275004 2 78 134 544 297002 71 10 18 30 202002 57 12 18 30 202002 57 12 18 30 203002 71 106 285 31 291002 71 106 285 32 26 298003 79 42 49 42 49 200002 80 6 7 7	080005 91 56 164 33 080005 82 28 373 46 087001 68 10 26 31 085001 77 8 20 30 03001 2 79 6 14 29 030002 75 9 17 24 075004 2 78 134 544 38 087002 71 10 18 22 078001 83 18 30 20 070002 57 12 18 17 081002 71 106 285 31 081002 71 106 285 31 08003 79 42 49 7 000002 80 6 7 7	C80005 91 56 164 33 50 C80005 82 28 373 46 35 C80001 68 10 26 31 50 C85001 77 8 20 30 50 C303001 2 79 6 14 29 50 C304002 79 68 154 28 50 C95004 2 75 9 17 24 50 C975004 2 78 134 544 38 35 C97002 71 10 18 22 50 C78001 83 18 30 20 50 C02002 57 12 18 17 50 291002 71 106 285 31 35 203002 73 22 26 8 50 298003 79 42 49 7 <t< td=""></t<>

For a better reflection of the contractors' performance in the assessment period, only the CPR results of Contractors whose installations inspected by EMSD for 5 times or more will be included in the table. It does not include (a) the contractors whose installations inspected by EMSD are less than 5 times and (b) contractors who do not undertake any lift maintenance work during the assessment period. (a) Contractors whose installations inspected by EMSD were less than 5 times during the assessment period

Name of Registered Lift Contractor	Contractor No.
Loedige Asia Limited	RLC07001
Taizoom Elevator Company (H.K.) Limited	RLC10001

Note 1:

(b) Contractors who did not undertake any lift maintenance work during the assessment period

Name of Registered Lift Contractor	Contractor No.
CNIM Hong Kong Ltd.	RLC88004
Group Creation International Limited	RLC04001
Hang Fung Lift Ltd.	RLC88003
Holake (HK) Ltd.	RLC76001
MTR Corporation Ltd.	RLC78003
Ryoden Elevator Company Limited	RLC64001
Whole Safe Ltd.	RLC92001

Performance Index (Full mark of 100) = Maintenance Index (0 to 50 marks) + Safety Index (0 to 50 marks); Maintenance Index = 50 x (1- cumulated maintenance performance monitoring points / number of inspections in the period); Safety Index = 50 - cumulated safety performance monitoring points (each critical safety non-compliant item with 15 Points). The cumulated performance monitoring points are valid for 12 months. Details of the maintenance and safety items can be observed from http://www.emsd.gov.hk/emsd/e_download/pps/circular/A3/2_2011.pdf. Note 2 :

Contractor whose installations inspected by EMSD was less than 5 times in the last reporting period and was not included in last CPR list. Note 3: