

Contractors' Performance Rating (CPR) of Registered Lift Contractor (From September 2010 to August 2011) (Note 1) (in alphabetical order)

Name of Registered Lift Contractor	Contractor No.	No. of prosecution cases in the assessment period	No. of disciplinary cases in the assessment period	Previous Performance Index (June 2010 to May 2011)	September 2010 to August 2011				
					Cumulated Maintenance PM Points	No. of Lifts Inspected	Maintenance Index (Note 2)	Safety Index (Note 2)	Performance Index
Anlev Elex Elevator Ltd.	RLC92004			89	14	49	36	50	86
Antonfield Engineering Co., Ltd.	RLC95002			70	3	18	42	50	92
Associated Engineers, Ltd.	RLC01003			100	0	8	50	50	100
Association Electrical Engineering Limited	RLC02003			94	0	29	50	50	100
Ben Fung Machineries & Engineering Ltd	RLC73001			100	0	40	50	50	100
Cheerwell Engineering Limited	RLC96002			100	0	11	50	50	100
Chevalier (HK) Limited	RLC69001			97	23	451	47	50	97
Chun Ming Elevator Co. Ltd.	RLC93002	1		78	6	42	43	35	78
Chun Ming Engineering Co. Ltd.	RLC88002		1	100	8	90	46	50	96
CKP Building Service Systems Ltd.	RLC85001			92	6	6	0	50	50
Elevator Parts Engineering Company Limited	RLC78001			70	18	35	24	50	74
Eugene Engineering Co. Limited	RLC03002			50	4	27	43	50	93
Fujitec (HK) Co. Ltd.	RLC85005			90	61	402	42	50	92
Hitachi Elevator Engineering Co. (HK) Ltd.	RLC67001			94	12	155	46	35	81
Hoi Fai Lift Engineering & Services Ltd.	RLC87006			100	0	10	50	50	100
Holake Hong Kong Lifts Ltd.	RLC80005			86	41	203	40	50	90
Hongkong International Terminals Limited	RLC01004			100	0	13	50	50	100
Jekco Elevators Ltd.	RLC97001			77	20	35	21	50	71
KONE Elevator (HK) Ltd.	RLC87001			90	60	288	40	50	90
Lighthouse Elevator Engineering Limited	RLC98003			56	52	59	6	50	56
Mitsubishi Elevator Hong Kong Company Limited	RLC88005			82	8	398	49	50	99
Nikkin Lifts & Escalators Limited	RLC91002			80	89	191	27	50	77
Otis Elevator Company (HK) Limited	RLC75004	2		68	198	582	33	50	83
Rich Mark Engineering Limited	RLC99001			100	3	51	47	50	97
Ring Hing Engineering Services Co., Ltd.	RLC97004			94	24	71	33	50	83
Ryoden Lift Services Limited	RLC99002			87	6	16	31	50	81
Schindler Lifts (Hong Kong) Ltd	RLC74002			92	95	460	40	50	90
Shan On Engineering Company Limited	RLC73002			97	6	61	45	50	95
Shineford Engineering Limited	RLC97002			100	0	17	50	50	100
Sigma Elevator (HK) Ltd.	RLC04002			70	78	131	20	50	70
Southa Technical Limited	RLC01002			88	4	16	38	50	88
Sun Fai Engineering & Equipment Co., Ltd.	RLC02002			65	12	16	13	50	63
Tak Lee Elevator Engineering Co., Ltd.	RLC02001			100	0	9	50	50	100
Techfaith Engineering Limited	RLC00002			100	20	5	0	50	50
The Express Lift Company Limited	RLC94001			91	24	143	42	50	92
ThyssenKrupp Elevator (HK) Limited	RLC96001		1	97	20	157	44	50	94
Toki Elevator Engineering Ltd.	RLC85002			84	27	48	22	50	72
Vertex Engineering Limited	RLC00001			100	0	11	50	50	100

Note 1 : For better reflection of the contractors' performance in the assessment period, only the CPR results of Contractors whose installations inspected by EMSD for 5 times or more will be included in the table. It does not include (a) the contractors whose installations inspected by EMSD are less than 5 times and (b) contractors who do not undertake any lift maintenance work during the assessment period.

(a) Contractors whose installations inspected by EMSD were less than 5 times during the assessment period

Name of Registered Lift Contractor	Contractor No.
Amanti (HK) Lift & Escalator Engineering Limited	RLC03001
Loedige Asia Limited	RLC07001
Taizoom Elevator Company (H.K.) Limited	RLC10001

(b) Contractors who did not undertake any lift maintenance work during the assessment period

Name of Registered Lift Contractor	Contractor No.
CNIM Hong Kong Ltd.	RLC88004
Group Creation International Limited	RLC04001
Holake (HK) Ltd.	RLC76001
MTR Corporation Ltd.	RLC78003
Ryoden Elevator Company Limited	RLC64001
Whole Safe Ltd.	RLC92001

Note 2 : Performance Index (Full mark of 100) = Maintenance Index (0 to 50 marks) + Safety Index (0 to 50 marks); Maintenance Index = 50 x (1 - cumulated maintenance performance monitoring points / number of inspections in the period); Safety Index = 50 - cumulated safety performance monitoring points (each critical safety non-compliant item with 15 Points). The cumulated performance monitoring points are valid for 12 months. Details of the maintenance and safety items can be observed from http://www.emsd.gov.hk/emsd/e_download/pps/circular/A3/2_2011.pdf.