Contractors' Performance Rating (CPR) of Registered Lift Contractor (From March 2011 to February 2012) (Note 1) (in alphabetical order)

					March 2011 to February 2012				
Name of Contractors	Contractor No.	No. of prosecution cases in the assessment period	No. of disciplinary cases in the assessment period	Previous Performance Index (December 2010 to November 2011)	•				
					Cumulative Maintenance PM Points	No. of Lifts Inspected	Maintenance Index (Note 2)	Safety Index (Note 2)	Performance Index
Anlev Elex Elevator Ltd.	RLC92004			93	6	80	46	50	96
Antonfield Engineering Co., Ltd.	RLC95002			100	0	18	50	50	100
Associated Engineers, Ltd.	RLC01003			100	0	6	50	50	100
Association Electrical Engineering Limited	RLC02003			100	0	36	50	50	100
Ben Fung Machineries & Engineering Ltd	RLC73001			100	18	24	13	50	63
Cheerwell Engineering Limited	RLC96002			100	0	13	50	50	100
Chevalier (HK) Limited	RLC69001			99	10	494	49	50	99
Chun Ming Elevator Co. Ltd.	RLC93002	1		89	8	28	36	50	86
Chun Ming Engineering Co. Ltd.	RLC88002		1	95	8	94	46	50	96
CKP Building Service Systems Ltd.	RLC85001			70	12	9	0	50	50
Elevator Parts Engineering Company Limited	RLC78001			90	0	37	50	50	100
Eugene Engineering Co. Limited	RLC03002			93	4	34	44	50	94
Fujitec (HK) Co. Ltd.	RLC85005			99	0	370	50	50	100
Hitachi Elevator Engineering Co. (HK) Ltd.	RLC67001			82	9	191	48	35	83
Hoi Fai Lift Engineering & Services Ltd.	RLC87006			100	0	10	50	50	100
Holake Hong Kong Lifts Ltd.	RLC80005			96	12	129	45	50	95
Hongkong International Terminals Limited	RLC01004			100	0	18	50	50	100
Jekco Elevators Ltd.	RLC97001			72	16	32	25	50	75
KONE Elevator (HK) Ltd.	RLC87001			92	36	224	42	50	92
Lighthouse Elevator Engineering Limited	RLC98003			70	48	77	19	50	69
Mitsubishi Elevator Hong Kong Company Limited	RLC88005			99	0	613	50	50	100
Nikkin Lifts & Escalators Limited	RLC91002			51	91	261	33	20	53
Otis Elevator Company (HK) Limited	RLC75004	1		86	114	590	40	50	90
Rich Mark Engineering Limited	RLC99001			98	3	58	47	50	97
Ring Hing Engineering Services Co., Ltd.	RLC97004			50	65	82	10	50	60
Ryoden Lift Services Limited	RLC99002			100	0	26	50	50	100
Schindler Lifts (Hong Kong) Ltd	RLC74002			91	62	451	43	50	93
Shan On Engineering Company Limited	RLC73002			95	6	72	46	50	96
Shineford Engineering Limited	RLC97002			57	24	17	0	50	50
Sigma Elevator (HK) Ltd.	RLC04002			80	50	89	22	50	72
Sun Fai Engineering & Equipment Co., Ltd.	RLC02002			100	0	18	50	35	85
Techfaith Engineering Limited	RLC00002			50	58	12	0	50	50
The Express Lift Company Limited	RLC94001			85	38	145	37	50	87
ThyssenKrupp Elevator (HK) Limited	RLC96001		1	73	66	142	27	50	77
Toki Elevator Engineering Ltd.	RLC85002			71	15	37	30	50	80
Vertex Engineering Limited	RLC00001			100	0	20	50	50	100

Note 1 :

For a better reflection of the contractors' performance in the assessment period, only the CPR results of Contractors whose installations have been inspected by EMSD for 5 times or more will be included in the table. It does not include (a) the contractors whose installations inspected by EMSD are less than 5 times and (b) contractors who do not undertake any lift maintenance work during the assessment period.

(a) Contractors whose installations have been inspected by EMSD were less than 5 times during the assessment period

Name of Registered Lift Contractor	Contractor No.		
Amanti (HK) Lift & Escalator Engineering Limited	RLC03001		
Loedige Asia Limited	RLC07001		
Taizoom Elevator Company (H.K.) Limited	RLC10001		
Tak Lee Elevator Engineering Co., Ltd.	RLC02001		

(b) Contractors who did not undertake any lift maintenance work during the assessment period

Name of Registered Lift Contractor	Contractor No.		
Group Creation International Limited	RLC04001		
Holake (HK) Ltd.	RLC76001		
MTR Corporation Ltd.	RLC78003		
Ryoden Elevator Company Limited	RLC64001		
Whole Safe Ltd.	RLC92001		

Note 2

Performance Index (Full mark of 100) = Maintenance Index (0 to 50 marks) + Safety Index (0 to 50 marks); Maintenance Index = 50 x (1- cumulative maintenance performance monitoring points / number of inspections in the period); Safety Index = 50 - cumulative safety performance monitoring points (each critical safety non-compliant item with 15 Points). The cumulative performance monitoring points are valid for 12 months. Details of the maintenance and safety items can be observed from http://www.emsd.gov.hk/emsd/e_download/pps/circular/A3/3_2012.pdf.